

Registration No.	Damage costs estimated	Damage Date	Descr. Cause	Descr. Damage	Name Body Repair Centrum	Brand
5AD7326	5 717 Kč	14-03-2019	Damage caused by stones	front windscreen	čelní sklo	Toyota
5AD7326	18 669 Kč	22-01-2020	Crashed	left side	levá strana	Toyota
5AD7326	1 500 Kč	30-07-2021	Damage caused by stones	front windscreen	čelní sklo	Toyota
5AD7326	0 Kč	20-09-2021	Crashed	front side	přední strana	Toyota
5AD7326	78 011 Kč	20-09-2021	Crashed	front side	přední strana	Toyota
5AD7326	12 008 Kč	02-09-2022	Crashed	rear bumper	zadní nárazník	Toyota
5AD7326	7 233 Kč	07-12-2022	Crashed	right threshold	pravý práh	Toyota
5AD7326	24 189 Kč	27-02-2023	Crashed	left side	levá strana	Toyota
5AD7326	10 788 Kč	16-03-2023	Crashed	rear right door	pravé zadní dveře	Toyota
5AD7326	8 982 Kč	21-03-2023	Vandalism	rear right	v pravo v zadu	Toyota
5AD7326	0 Kč	28-03-2023	Damage caused by stones	front windscreen	čelní sklo	Toyota
5AD7326	0 Kč	12-04-2023	unknown	front side	přední strana	Toyota
5AD7326	8 288 Kč	19-09-2023	Damage caused by stones	front windscreen	čelní sklo	Toyota
5AD7326	0 Kč	19-09-2023	Crashed	front right	vpředu vpravo	Toyota
5AD7326	0 Kč	05-10-2023	Crashed	rear right	v pravo v zadu	Toyota
5AH9931	28 166 Kč	11-08-2019	Crashed	left side	levá strana	Skoda
5AH9931	17 267 Kč	04-03-2020	Crashed	rear bumper	zadní nárazník	Skoda
5AH9931	6 076 Kč	04-04-2021	Crashed	rear left	v levo v zadu	Skoda
5AH9931	2 188 Kč	03-03-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
5AH9931	23 400 Kč	27-11-2022	Crashed	rear side	zadní strana	Skoda
5AI4235	63 913 Kč	04-10-2017	Animal crossing	right side	pravá strana	Ford
5AI4235	3 800 Kč	14-03-2022	Damage caused by stones	front windscreen	čelní sklo	Ford
5AI4235	10 041 Kč	27-04-2022	Damage caused by stones	front windscreen	čelní sklo	Ford
5AI4235	10 041 Kč	12-10-2022	Damage caused by stones	front windscreen	čelní sklo	Ford
5AI4235	10 722 Kč	06-02-2023	Damage caused by stones	front windscreen	čelní sklo	Ford
5AI4235	10 722 Kč	10-07-2023	Damage caused by stones	front windscreen	čelní sklo	Ford
5AI4235	0 Kč	11-01-2024	Crashed	rear left	v levo v zadu	Ford
5AN9704	19 108 Kč	25-09-2016	Crashed	front side	přední strana	Fiat
5AN9704	0 Kč	13-11-2016	Inspection	front right door	pravé přední dveře	Fiat
5AN9704	13 624 Kč	14-11-2016	Inspection	front right door	pravé přední dveře	Fiat
5AN9704	5 680 Kč	21-11-2016	Inspection	rear right	v pravo v zadu	Fiat

5AN9704	4 782 Kč	23-11-2016	Crashed	rear bumper	zadní nárazník	Fiat
5AN9704	13 807 Kč	28-04-2017	unknown	rear side	zadní strana	Fiat
5AN9704	5 962 Kč	15-08-2017	Parking damage	left side	levá strana	Fiat
5AN9704	11 986 Kč	16-01-2018	unknown	rear left	v levo v zadu	Fiat
5AN9704	5 259 Kč	17-02-2019	Inspection	front right	vpředu vpravo	Fiat
5AN9704	8 650 Kč	06-06-2020	Crashed	right side	pravá strana	Fiat
5AN9704	11 629 Kč	15-06-2022	Crashed	rear side	zadní strana	Fiat
5AN9704	14 225 Kč	26-12-2022	Crashed	front right	vpředu vpravo	Fiat
5AN9704	13 930 Kč	05-12-2023	Crashed	rear side	zadní strana	Fiat
5AN9704	0 Kč	05-12-2023	unknown	left side	levá strana	Fiat
6AB5068	7 708 Kč	02-01-2019	Damage caused by stones	front windscreen	čelní sklo	Ford
6AB5068	2 070 Kč	24-01-2022	Crashed	rear left	v levo v zadu	Ford
6AB5068	5 511 Kč	23-01-2023	Crashed	wing mirror left	levé zrcátko	Ford
6AC2162	17 902 Kč	26-03-2018	Collision kerbstone	right threshold	pravý práh	Skoda
6AC2162	4 556 Kč	23-04-2018	Nature forces	front windscreen	čelní sklo	Skoda
6AC2162	6 774 Kč	25-11-2019	Crashed	right side	pravá strana	Skoda
6AC2162	6 500 Kč	23-05-2023	Crashed	front side	přední strana	Skoda
6AC2162	6 000 Kč	23-05-2023	Crashed	front left	vpředu vlevo	Skoda
6AC2162	6 000 Kč	23-05-2023	Crashed	front right	vpředu vpravo	Skoda
6AC2162	7 000 Kč	07-07-2023	Crashed	right threshold	pravý práh	Skoda
6AC2162	1 275 Kč	30-07-2023	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
6AC2162	6 500 Kč	12-08-2023	Crashed	bonnet	kapota	Skoda
6AC2162	13 500 Kč	24-08-2023	Crashed	rear left	v levo v zadu	Skoda
6AC2162	6 000 Kč	05-01-2024	Crashed	rear side	zadní strana	Skoda
6AC2162	0 Kč	22-01-2024	Crashed	rear door left	zadní dveře vlevo	Skoda
6AD1928	6 832 Kč	07-07-2020	Damage caused by stones	front windscreen	čelní sklo	Ford
6AD1928	0 Kč	06-08-2021	Crashed	no damage/unknown	žádné poškození / neznámé	Ford
6AD1928	8 835 Kč	09-01-2023	Damage caused by stones	front windscreen	čelní sklo	Ford
6AD1928	8 834 Kč	27-04-2023	Damage caused by stones	front windscreen	čelní sklo	Ford
6AD1928	12 551 Kč	18-12-2023	Damage caused by stones	front windscreen	čelní sklo	Ford
6AF5153	2 480 Kč	28-08-2017	Vandalism	all around	všude okolo	Ford
6AF5153	48 750 Kč	13-12-2020	Animal crossing	left side	levá strana	Ford
6AF5153	3 579 Kč	23-03-2023	unknown	roof	střecha	Ford
6AF5153	1 135 Kč	23-03-2023	unknown	right wing mirror	pravé křídlo zrcadlo	Ford
6AF5153	18 047 Kč	28-02-2024	Crashed	left side	levá strana	Ford
6AF5153	23 642 Kč	04-03-2024	Crashed	all around	všude okolo	Ford
6AH8630	19 117 Kč	25-11-2017	Crashed	right side	pravá strana	Peugeot

6AH8630	14 968 Kč	11-04-2018	Damage caused by stones	front windscreen	čelní sklo	Peugeot
6AH8630	54 870 Kč	18-06-2018	Crashed	right side	pravá strana	Peugeot
6AH8630	5 763 Kč	21-09-2019	Crashed	rear left	v levo v zadu	Peugeot
6AH8630	0 Kč	21-07-2021	Crashed	rear right	v pravo v zadu	Peugeot
6AH8630	8 812 Kč	21-07-2021	Crashed	rear right	v pravo v zadu	Peugeot
6AH8630	9 600 Kč	05-02-2024	Damage caused by stones	front windscreen	čelní sklo	Peugeot
6AL6258	7 331 Kč	21-04-2022	unknown	front bumper	přední nárazník	Skoda
6AL6258	0 Kč	23-03-2023	Crashed	front left	vpředu vlevo	Skoda
6AL6258	0 Kč	16-11-2023	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
6AL6258	17 279 Kč	21-01-2024	Crashed	rear right	v pravo v zadu	Skoda
6AL6258	0 Kč	23-01-2024	Damage caused by stones	front windscreen	GFB AUTOSKLO SERVIS, S.R.O.	2016355033
6AN3187	0 Kč	30-11-2018	Crashed	rear side	zadní strana	Peugeot
6AN3187	45 716 Kč	24-09-2019	Parking damage	left side	levá strana	Peugeot
6AN3187	0 Kč	09-03-2021	Crashed	no damage/unknown	žádné poškození / neznámé	Peugeot
6AN3187	0 Kč	04-08-2023	unknown	damage dashboard	řídící panel poškození	Peugeot
6AN3187	0 Kč	11-03-2024	Damage caused by stones	front windscreen	čelní sklo	Peugeot
6AR4796	7 126 Kč	30-08-2019	Inspection	right wing mirror	pravé křídlo zrcadlo	Skoda
6AR4796	60 663 Kč	01-01-2021	unknown	all around	všude okolo	Skoda
6AR4796	44 408 Kč	25-02-2021	Crashed	rear door left	zadní dveře vlevo	Skoda
6AR4796	7 298 Kč	22-04-2022	Rodent	cabling	kabeláž	Skoda
6AR4796	26 663 Kč	25-05-2023	Crashed	left side	levá strana	Skoda
6AR4796	30 905 Kč	25-05-2023	unknown	right side	pravá strana	Skoda
6AR4796	42 596 Kč	28-12-2023	unknown	all around	všude okolo	Skoda
6AS1466	0 Kč	27-02-2019	Crashed	front side	přední strana	Ford
6AS1466	0 Kč	27-02-2019	Crashed	front side	přední strana	Ford
6AS1466	51 237 Kč	15-11-2023	Crashed	all around	všude okolo	Ford
6AS1466	34 608 Kč	09-12-2023	unknown	all around	všude okolo	Ford
6AS1466	9 902 Kč	14-12-2023	Crashed	rear left	v levo v zadu	Ford
6AS1466	19 757 Kč	06-01-2024	Crashed	front side	přední strana	Ford
6AS4302	0 Kč	20-01-2021	Animal crossing	front side	přední strana	Skoda
6AS4302	8 260 Kč	26-02-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AS4302	8 260 Kč	10-08-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AS4302	30 000 Kč	11-01-2024	Crashed	front side	přední strana	Skoda
6AS4302	9 238 Kč	11-01-2024	Crashed	rear side	zadní strana	Skoda
6AS4302	0 Kč	11-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AS6770	46 598 Kč	13-03-2019	Crashed	right side	pravá strana	Skoda

6AS6770	4 831 Kč	22-04-2020	Parking damage	front windscreen	čelní sklo	Skoda
6AS6770	16 633 Kč	25-11-2021	unknown	wheel housing	skříň kola	Skoda
6AS9952	130 895 Kč	05-06-2018	Crashed	front side	přední strana	Skoda
6AS9952	28 587 Kč	27-08-2020	Crashed	front right	vpředu vpravo	Skoda
6AS9952	39 397 Kč	30-01-2022	Nature forces	all around	všude okolo	Skoda
6AS9952	0 Kč	31-01-2022	unknown	front right door	pravé přední dveře	Skoda
6AS9952	1 500 Kč	02-04-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AS9952	19 913 Kč	29-11-2023	Crashed	front left	vpředu vlevo	Skoda
6AS9952	1 500 Kč	05-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AT3504	1 500 Kč	17-04-2018	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AT3504	5 496 Kč	05-04-2019	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AT3504	5 496 Kč	12-10-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
6AT3504	1 339 Kč	17-08-2021	Broken	cabling	kabeláž	Skoda
6AT3504	0 Kč	09-08-2023	Crashed	front side	přední strana	Skoda
6AT3504	80 503 Kč	18-08-2023	Crashed	left side	levá strana	Skoda
6AU6228	7 001 Kč	14-05-2019	Inspection	front left	vpředu vlevo	Skoda
6AU6228	32 520 Kč	25-09-2021	Crashed	right side	pravá strana	Skoda
6AU6228	0 Kč	26-01-2023	Crashed	right side	pravá strana	Skoda
6AU6228	6 500 Kč	24-04-2023	Crashed	front side	přední strana	Skoda
6AU6228	6 000 Kč	24-04-2023	Crashed	rear right	v pravo v zadu	Skoda
6AU6228	7 000 Kč	24-07-2023	Crashed	threshold left	práh vlevo	Skoda
6AU6228	6 500 Kč	29-11-2023	Crashed	rear side	zadní strana	Skoda
6AU6228	0 Kč	09-02-2024	Crashed	rear right door	pravé zadní dveře	Skoda
6AV8952	49 805 Kč	10-12-2021	Crashed	rear bumper	zadní nárazník	Kia
6AV8952	0 Kč	07-10-2022	Crashed	front side	přední strana	Kia
6AV8952	30 333 Kč	07-10-2022	Crashed	front bumper	přední nárazník	Kia
6AV8952	30 000 Kč	23-02-2024	unknown	rear bumper	zadní nárazník	Kia
6AX4718	19 382 Kč	17-12-2023	Crashed	rear right	v pravo v zadu	Skoda
6AX7590	7 274 Kč	21-02-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
6AX7590	0 Kč	20-05-2022	Crashed	roof	střecha	Volkswagen
6AZ5336	8 139 Kč	23-01-2024	Crashed	left side	levá strana	Skoda
6AZ8697	70 235 Kč	19-03-2019	Crashed	rear side	zadní strana	Volkswagen
6J48608	25 718 Kč	29-09-2021	Crashed	rear bumper	zadní nárazník	Skoda
6J48608	0 Kč	18-12-2022	Crashed	front side	přední strana	Skoda
6J48608	45 463 Kč	18-12-2022	Crashed	front side	přední strana	Skoda
6J48608	0 Kč	25-05-2023	Crashed	rear right	v pravo v zadu	Skoda
6J48608	58 124 Kč	02-02-2024	unknown	all around	všude okolo	Skoda
7AA2431	27 354 Kč	13-11-2023	Crashed	rear left	v levo v zadu	Skoda

7AA2431	0 Kč	13-11-2023	Crashed	front left	vpředu vlevo	Skoda
7AA2431	30 511 Kč	04-12-2023	Crashed	front right	vpředu vpravo	Skoda
7AA2431	13 869 Kč	31-12-2023	Crashed	rear right	v pravo v zadu	Skoda
7AB1303	4 761 Kč	11-03-2019	Nature forces	front windscreen	čelní sklo	Skoda
7AB1303	8 001 Kč	30-09-2019	Nature forces	bonnet	kapota	Skoda
7AB1303	5 275 Kč	28-04-2020	Parking damage	head lights	přední světla	Skoda
7AB1303	4 761 Kč	22-07-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AB1303	1 347 Kč	16-01-2023	Rodent	cabling	kabeláž	Skoda
7AB1303	29 519 Kč	21-12-2023	Crashed	front right door	pravé přední dveře	Skoda
7AB1303	5 896 Kč	05-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AB1303	55 000 Kč	01-02-2024	Nature forces	hail damage	RUPEXIM S.R.O.	2018115065
7AC4971	8 977 Kč	12-03-2020	Inspection	front windscreen	čelní sklo	Skoda
7AC4971	22 567 Kč	25-10-2020	Crashed	wing mirror left	levé zrcátko	Skoda
7AC4971	16 225 Kč	20-07-2022	unknown	all around	všude okolo	Skoda
7AC4971	0 Kč	15-11-2023	Nature forces	hail damage	krupobití	Skoda
7AD4100	0 Kč	05-12-2018	Crashed	front left	vpředu vlevo	Citroen
7AD4100	23 581 Kč	05-12-2018	Crashed	front left	vpředu vlevo	Citroen
7AD4100	5 312 Kč	26-06-2019	Damage caused by stones	front windscreen	čelní sklo	Citroen
7AD4100	2 300 Kč	17-10-2019	Damage caused by stones	front windscreen	čelní sklo	Citroen
7AD4100	5 312 Kč	23-02-2021	Damage caused by stones	front windscreen	čelní sklo	Citroen
7AD4100	1 500 Kč	18-06-2021	Damage caused by stones	front windscreen	čelní sklo	Citroen
7AD4100	2 208 Kč	11-04-2023	Vandalism	side window	boční okno	Citroen
7AD4100	0 Kč	07-07-2023	Crashed	front left	vpředu vlevo	Citroen
7AD4100	0 Kč	07-08-2023	Crashed	front bumper	přední nárazník	Citroen
7AD4100	0 Kč	12-08-2023	Animal crossing	front bumper	přední nárazník	Citroen
7AD4100	14 293 Kč	12-08-2023	unknown	all around	všude okolo	Citroen
7AD4100	43 329 Kč	12-08-2023	unknown	front side	přední strana	Citroen
7AD4100	12 162 Kč	16-08-2023	Damage caused by stones	front windscreen	čelní sklo	Citroen
7AD4100	14 989 Kč	16-08-2023	Nature forces	all around	všude okolo	Citroen
7AD4100	4 536 Kč	25-08-2023	unknown	right side	pravá strana	Citroen
7AD4100	0 Kč	05-09-2023	Crashed	right side	pravá strana	Citroen
7AE0545	2 300 Kč	19-06-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AE0545	8 605 Kč	18-10-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda

7AE0545	17 733 Kč	16-03-2023	unknown	right side	pravá strana	Skoda
7AE0545	0 Kč	06-09-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AE0545	7 454 Kč	29-09-2023	Crashed	rear side	zadní strana	Skoda
7AE0545	10 948 Kč	08-12-2023	unknown	front side	přední strana	Skoda
7AE0548	9 974 Kč	13-03-2019	Crashed	front right	vpředu vpravo	Skoda
7AE0548	47 908 Kč	26-04-2021	Animal crossing	front side	přední strana	Skoda
7AE0548	1 104 Kč	22-07-2021	Broken	cabling	kabeláž	Skoda
7AE0548	1 189 Kč	02-09-2021	Rodent	cabling	kabeláž	Skoda
7AE0548	31 692 Kč	25-11-2021	Crashed	rear side	zadní strana	Skoda
7AE9181	21 004 Kč	11-04-2022	Crashed	rear bumper	zadní nárazník	Skoda
7AE9181	25 392 Kč	03-01-2024	Animal crossing	front side	přední strana	Skoda
7AE9373	9 041 Kč	30-06-2021	unknown	rear right	v pravo v zadu	Skoda
7AE9373	16 117 Kč	02-08-2021	Crashed	front bumper	přední nárazník	Skoda
7AE9373	0 Kč	15-11-2022	Crashed	rear left	v levo v zadu	Skoda
7AE9373	50 980 Kč	21-12-2022	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
7AF1576	17 389 Kč	11-03-2019	Inspection	front left	vpředu vlevo	Ford
7AF1576	6 982 Kč	17-03-2019	Inspection	rear side	zadní strana	Ford
7AF1576	23 377 Kč	16-10-2019	Inspection	rear left	v levo v zadu	Ford
7AF1576	28 229 Kč	28-12-2019	Crashed	right side	pravá strana	Ford
7AF1576	12 790 Kč	15-03-2020	Crashed	rear right	v pravo v zadu	Ford
7AF1576	10 776 Kč	28-04-2020	Parking damage	rear left	v levo v zadu	Ford
7AF1576	0 Kč	06-05-2020	Obstacle	engine cover	kryt motoru	Ford
7AF1576	3 013 Kč	06-05-2020	Obstacle	right threshold	pravý práh	Ford
7AF1576	0 Kč	01-06-2020	Crashed	engine damage	poškození motoru	Ford
7AF1576	8 500 Kč	27-06-2020	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Ford
7AF1576	7 535 Kč	07-03-2021	unknown	rear left	v levo v zadu	Ford
7AF1576	32 835 Kč	14-04-2021	unknown	front left	vpředu vlevo	Ford
7AF1576	9 296 Kč	15-04-2021	unknown	left side	levá strana	Ford
7AF1576	14 348 Kč	29-08-2021	Crashed	right side	pravá strana	Ford
7AF1576	7 854 Kč	21-09-2021	Crashed	rear right door	pravé zadní dveře	Ford
7AF1576	2 Kč	26-09-2021	Vandalism	rear left	v levo v zadu	Ford
7AF1576	18 722 Kč	29-09-2021	Crashed	left side	levá strana	Ford
7AF1576	17 818 Kč	02-10-2021	Crashed	wing mirror left	levé zrcátko	Ford
7AF1576	5 707 Kč	08-10-2021	unknown	rear door left	zadní dveře vlevo	Ford
7AF1576	8 132 Kč	07-02-2022	unknown	rear right	v pravo v zadu	Ford
7AF1576	22 015 Kč	21-02-2022	unknown	front right	vpředu vpravo	Ford
7AF1576	28 089 Kč	10-08-2022	Crashed	right side	pravá strana	Ford
7AF1576	11 747 Kč	15-08-2022	Crashed	left side	levá strana	Ford
7AF1576	21 279 Kč	17-08-2022	Vandalism	roof	střecha	Ford
7AF1576	2 Kč	22-08-2022	Crashed	front left	vpředu vlevo	Ford
7AF1576	2 Kč	22-08-2022	Crashed	front door left	přední dveře vlevo	Ford
7AF2400	10 830 Kč	08-09-2022	Crashed	rear left	v levo v zadu	Skoda

7AF2400	9 375 Kč	18-12-2023	Crashed	front bumper	přední nárazník	Skoda
7AF5529	76 265 Kč	27-12-2018	Crashed	rear side	zadní strana	Toyota
7AF5529	14 955 Kč	01-04-2019	Crashed	rear bumper	zadní nárazník	Toyota
7AF5529	25 639 Kč	05-10-2022	unknown	front bumper	přední nárazník	Toyota
7AF5529	26 768 Kč	20-10-2022	unknown	rear bumper	zadní nárazník	Toyota
7AF5529	41 884 Kč	02-11-2022	unknown	rear side	zadní strana	Toyota
7AH1782	4 755 Kč	04-09-2019	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AH1782	41 333 Kč	06-04-2021	Crashed	left side	levá strana	Skoda
7AH1782	0 Kč	19-05-2021	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
7AH1782	19 325 Kč	15-08-2023	Crashed	all around	všude okolo	Skoda
7AH2993	12 316 Kč	01-03-2023	Damage caused by stones	front windscreen	čelní sklo	Ford
7AH3636	33 149 Kč	06-06-2023	Crashed	front side	přední strana	Volkswagen
7AH3636	26 474 Kč	15-08-2023	Crashed	rear side	zadní strana	Volkswagen
7AH3636	802 Kč	24-10-2023	Crashed	rear side	zadní strana	Volkswagen
7AH3636	6 422 Kč	11-01-2024	Crashed	right side	pravá strana	Volkswagen
7AH7554	0 Kč	25-11-2020	Crashed	all around	všude okolo	Kia
7AH7554	25 108 Kč	25-11-2020	Crashed	all around	všude okolo	Kia
7AH7554	10 616 Kč	03-12-2023	unknown	rear right	v pravo v zadu	Kia
7AH7554	0 Kč	07-12-2023	unknown	rear left	v levo v zadu	Kia
7AH7554	0 Kč	09-01-2024	unknown	front bumper	přední nárazník	Kia
7AH7554	22 801 Kč	06-02-2024	unknown	left side	levá strana	Kia
7AH7554	24 276 Kč	06-02-2024	Crashed	rear side	zadní strana	Kia
7AI7616	0 Kč	30-05-2019	Crashed	front left	vpředu vlevo	Skoda
7AI7616	6 124 Kč	01-02-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AI7616	0 Kč	02-07-2021	Crashed	left side	levá strana	Skoda
7AI7616	0 Kč	02-07-2021	Crashed	left side	levá strana	Skoda
7AI7616	41 577 Kč	15-09-2022	Crashed	rear bumper	zadní nárazník	Skoda
7AI7616	8 693 Kč	21-09-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AI7616	11 632 Kč	23-02-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AI7616	1 500 Kč	08-08-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AI7616	0 Kč	07-09-2023	Crashed	left side	levá strana	Skoda
7AI7616	3 549 Kč	19-09-2023	unknown	right side	pravá strana	Skoda
7AI7616	0 Kč	19-09-2023	Crashed	right side	pravá strana	Skoda
7AI7616	10 990 Kč	25-09-2023	Crashed	front side	přední strana	Skoda
7AI7616	47 239 Kč	12-10-2023	Crashed	front right	vpředu vpravo	Skoda
7AI7616	6 907 Kč	13-10-2023	Crashed	front side	přední strana	Skoda
7AI7616	10 286 Kč	16-10-2023	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda

7AI7988	6 491 Kč	06-01-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AI9803	0 Kč	31-07-2019	Crashed	rear right	v pravo v zadu	Skoda
7AI9803	17 503 Kč	11-03-2020	Crashed	front side	přední strana	Skoda
7AI9803	8 093 Kč	06-04-2020	Parking damage	rear left	v levo v zadu	Skoda
7AI9803	36 883 Kč	11-07-2022	Crashed	front right	vpředu vpravo	Skoda
7AI9803	14 260 Kč	23-01-2024	Crashed	front left	vpředu vlevo	Skoda
7AI9803	45 807 Kč	29-01-2024	Crashed	rear right	v pravo v zadu	Skoda
7AI9804	25 152 Kč	12-05-2019	Crashed	front side	přední strana	Skoda
7AI9804	13 175 Kč	05-05-2020	Crashed	all around	všude okolo	Skoda
7AI9804	4 627 Kč	19-07-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AI9804	7 070 Kč	09-02-2022	Crashed	rear bumper	zadní nárazník	Skoda
7AI9804	8 025 Kč	26-10-2022	Crashed	front bumper	přední nárazník	Skoda
7AI9804	5 097 Kč	28-10-2022	Crashed	damage to interior	poškození interiéru	Skoda
7AI9804	14 828 Kč	31-10-2022	Crashed	rear right	v pravo v zadu	Skoda
7AI9804	0 Kč	13-07-2023	Crashed	front bumper	přední nárazník	Skoda
7AI9804	70 275 Kč	13-07-2023	Crashed	front side	přední strana	Skoda
7AI9804	24 895 Kč	31-01-2024	Crashed	all around	všude okolo	Skoda
7AI9950	0 Kč	23-12-2019	Crashed	no damage/unknown	žádné poškození / neznámé	Volkswagen
7AI9950	28 443 Kč	01-03-2022	unknown	rear side	zadní strana	Volkswagen
7AI9950	8 178 Kč	25-06-2022	Crashed	rear left	v levo v zadu	Volkswagen
7AI9950	6 942 Kč	21-02-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AI9951	61 043 Kč	16-04-2019	Crashed	rear side	zadní strana	Volkswagen
7AI9951	7 000 Kč	21-10-2019	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AI9951	5 961 Kč	06-02-2020	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AI9951	1 500 Kč	08-04-2021	unknown	cabling	kabeláž	Volkswagen
7AI9951	3 999 Kč	09-01-2024	Crashed	right wing mirror	pravé křídlo zrcadlo	Volkswagen
7AI9951	0 Kč	08-03-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AJ1118	10 479 Kč	26-08-2019	Inspection	rear bumper	zadní nárazník	Ford
7AJ2259	16 615 Kč	01-04-2021	Crashed	front side	přední strana	Skoda
7AJ2259	7 919 Kč	17-02-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ2259	0 Kč	12-04-2023	Crashed	front right	vpředu vpravo	Skoda
7AJ2259	18 260 Kč	15-11-2023	unknown	front side	přední strana	Skoda
7AJ2259	8 564 Kč	15-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ2259	0 Kč	14-01-2024	Crashed	rear side	zadní strana	Skoda
7AJ2259	0 Kč	02-02-2024	unknown	rear right	v pravo v zadu	Skoda

7AJ4188	5 332 Kč	31-05-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ4188	43 406 Kč	13-12-2023	unknown	all around	všude okolo	Skoda
7AJ7514	4 627 Kč	22-12-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7514	2 300 Kč	01-03-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7514	1 500 Kč	09-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7514	11 556 Kč	15-12-2023	unknown	all around	všude okolo	Skoda
7AJ7514	0 Kč	14-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7515	0 Kč	21-03-2019	Inspection	rear bumper	zadní nárazník	Skoda
7AJ7515	4 627 Kč	08-02-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7515	17 564 Kč	17-05-2021	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
7AJ7515	1 500 Kč	09-09-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7515	5 188 Kč	01-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7515	1 500 Kč	14-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AJ7515	58 236 Kč	26-02-2024	Crashed	right side	pravá strana	Skoda
7AJ9223	6 364 Kč	29-03-2021	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AJ9223	8 780 Kč	22-04-2021	Crashed	wing mirror left	levé zrcátko	Volkswagen
7AJ9223	10 040 Kč	04-01-2023	Rodent	cabling	kabeláž	Volkswagen
7AJ9424	13 406 Kč	16-12-2021	unknown	front left	vpředu vlevo	Skoda
7AJ9424	19 108 Kč	02-02-2023	Crashed	rear side	zadní strana	Skoda
7AK1217	7 491 Kč	17-05-2019	Rodent	engine damage	poškození motoru	Skoda
7AK1217	10 880 Kč	06-07-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AK1217	20 015 Kč	30-08-2023	Crashed	rear right	v pravo v zadu	Skoda
7AK2234	0 Kč	01-07-2020	Crashed	rear bumper	zadní nárazník	Volkswagen
7AK2234	32 903 Kč	01-07-2020	Crashed	rear bumper	zadní nárazník	Volkswagen
7AK2234	18 455 Kč	14-05-2021	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AK2234	1 500 Kč	21-02-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AK6020	3 705 Kč	23-07-2020	Vandalism	right side	pravá strana	Skoda
7AK6020	19 350 Kč	27-03-2023	Crashed	front left	vpředu vlevo	Skoda
7AK6020	8 564 Kč	01-04-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AK6020	28 394 Kč	04-05-2023	Vandalism	rear left	v levo v zadu	Skoda

7AK6020	3 126 Kč	23-10-2023	Theft	cabling	kabeláž	Skoda
7AK6020	1 820 Kč	25-11-2023	Rodent	cabling	kabeláž	Skoda
7AK6020	8 185 Kč	12-02-2024	unknown	front side	přední strana	Skoda
7AK6020	9 616 Kč	04-03-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AK6496	29 122 Kč	25-08-2020	Crashed	front right	vpředu vpravo	Skoda
7AK6496	0 Kč	21-10-2022	Crashed	rear right	v pravo v zadu	Skoda
7AK6496	19 208 Kč	21-10-2022	Crashed	rear right	v pravo v zadu	Skoda
7AK7480	9 649 Kč	09-01-2020	Vandalism	rear side	zadní strana	Peugeot
7AK7480	0 Kč	29-10-2021	Crashed	rear left	v levo v zadu	Peugeot
7AK7480	53 187 Kč	29-10-2021	Crashed	rear left	v levo v zadu	Peugeot
7AK7480	2 300 Kč	14-02-2023	Damage caused by stones	front windscreen	čelní sklo	Peugeot
7AK9330	8 835 Kč	29-05-2023	Crashed	front side	přední strana	Skoda
7AK9330	12 862 Kč	24-07-2023	unknown	right side	pravá strana	Skoda
7AK9330	10 802 Kč	07-09-2023	Crashed	rear left	v levo v zadu	Skoda
7AK9330	6 861 Kč	14-10-2023	Crashed	front left	vpředu vlevo	Skoda
7AK9330	15 000 Kč	12-12-2023	Crashed	rear right	v pravo v zadu	Skoda
7AK9330	0 Kč	04-01-2024	Crashed	rear side	zadní strana	Skoda
7AL5054	10 520 Kč	29-09-2019	Inspection	front side	přední strana	Volkswagen
7AL5054	6 159 Kč	27-07-2020	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AL5054	74 984 Kč	26-09-2022	Crashed	rear side	zadní strana	Volkswagen
7AL5054	49 977 Kč	04-09-2023	Crashed	all around	všude okolo	Volkswagen
7AL6126	20 195 Kč	07-04-2023	Crashed	rear side	zadní strana	Skoda
7AL8067	7 899 Kč	08-07-2020	Crashed	rear side	zadní strana	Volkswagen
7AL8067	2 049 Kč	08-12-2020	unknown	front right	vpředu vpravo	Volkswagen
7AL8067	0 Kč	09-02-2021	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Volkswagen
7AL8067	102 097 Kč	15-10-2021	Crashed	front side	přední strana	Volkswagen
7AL8067	59 107 Kč	04-07-2022	Crashed	right side	pravá strana	Volkswagen
7AL8067	0 Kč	03-10-2023	Rodent	cabling	kabeláž	Volkswagen
7AL8067	0 Kč	07-12-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AL9297	12 944 Kč	02-05-2020	Crashed	right side	pravá strana	Skoda
7AL9297	18 610 Kč	23-01-2022	unknown	rear door left	zadní dveře vlevo	Skoda
7AM5825	0 Kč	20-01-2020	Crashed	rear side	zadní strana	Peugeot
7AM5825	16 262 Kč	20-01-2020	Crashed	rear side	zadní strana	Peugeot
7AM5825	0 Kč	22-05-2020	Crashed	rear side	zadní strana	Peugeot
7AM5825	0 Kč	31-05-2020	Crashed	rear right door	pravé zadní dveře	Peugeot
7AM5825	0 Kč	30-06-2020	Crashed	left side	levá strana	Peugeot
7AM5825	11 764 Kč	30-01-2024	Crashed	rear right door	pravé zadní dveře	Peugeot
7AM5825	13 207 Kč	31-01-2024	Crashed	rear side	zadní strana	Peugeot
7AM5825	12 036 Kč	01-02-2024	Crashed	rear door left	zadní dveře vlevo	Peugeot
7AM5825	6 525 Kč	02-02-2024	Crashed	rear left	v levo v zadu	Peugeot
7AM6432	120 231 Kč	10-06-2020	Crashed	rear side	zadní strana	Volkswagen
7AM6432	0 Kč	08-03-2023	Crashed	front side	přední strana	Volkswagen
7AM6432	44 479 Kč	08-03-2023	Crashed	front side	přední strana	Volkswagen

7AM8640	43 273 Kč	14-09-2019	Crashed	left side	levá strana	Volkswagen
7AM8640	17 088 Kč	28-04-2021	Crashed	left side	levá strana	Volkswagen
7AM8902	7 365 Kč	04-09-2020	Crashed	wheel housing	skříň kola	Volkswagen
7AN1503	1 185 Kč	04-01-2022	Rodent	cabling	kabeláž	Skoda
7AN1503	32 826 Kč	31-10-2022	Crashed	all around	všude okolo	Skoda
7AN1503	71 951 Kč	28-11-2023	Crashed	front side	přední strana	Skoda
7AN7295	3 050 Kč	23-03-2020	Crashed	front bumper	přední nárazník	Skoda
7AN7411	0 Kč	17-10-2022	Crashed	rear right	v pravo v zadu	Skoda
7AN7411	17 689 Kč	09-11-2022	Crashed	rear right	v pravo v zadu	Skoda
7AN8239	6 740 Kč	15-06-2020	Damage caused by stones	front windscreen	čelní sklo	Renault
7AN8239	0 Kč	01-03-2023	unknown	engine damage	poškození motoru	Renault
7AN8239	13 116 Kč	01-03-2023	Crashed	engine cover	kryt motoru	Renault
7AN8239	144 395 Kč	25-05-2023	Crashed	left side	levá strana	Renault
7AN8239	0 Kč	06-11-2023	Crashed	left side	levá strana	Renault
7AN8239	110 000 Kč	06-11-2023	Crashed	left side	levá strana	Renault
7AN8447	12 760 Kč	12-02-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AP0658	0 Kč	18-08-2019	Crashed	front right	vpředu vpravo	Skoda
7AP0658	45 253 Kč	18-08-2019	Crashed	front left	vpředu vlevo	Skoda
7AP0658	8 700 Kč	01-02-2024	Crashed	rear side	zadní strana	Skoda
7AP0658	9 000 Kč	13-02-2024	Crashed	threshold left	práh vlevo	Skoda
7AP4657	16 875 Kč	05-01-2021	Rodent	cabling	kabeláž	Skoda
7AP4657	3 692 Kč	10-03-2024	Rodent	roof	střecha	Skoda
7AP5978	0 Kč	29-08-2019	Crashed	all around	všude okolo	Skoda
7AP5978	8 695 Kč	21-10-2021	Crashed	wing mirror left	levé zrcátko	Skoda
7AP5978	9 202 Kč	12-09-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AP5978	0 Kč	12-10-2023	Crashed	front left	AUTOCENTRUM BARTH A.S.	2019084035
7AR0755	5 746 Kč	04-11-2022	Crashed	rear left	v levo v zadu	Peugeot
7AR0755	0 Kč	06-11-2022	Crashed	rear left	v levo v zadu	Peugeot
7AR0755	7 632 Kč	06-11-2022	Crashed	rear left	v levo v zadu	Peugeot
7AR0755	0 Kč	09-10-2023	Crashed	rear side	zadní strana	Peugeot
7AR0755	0 Kč	27-10-2023	Crashed	front side	přední strana	Peugeot
7AR6776	21 017 Kč	29-12-2022	Crashed	rear left	v levo v zadu	Skoda
7AS0997	26 578 Kč	04-02-2022	unknown	front bumper	přední nárazník	Skoda
7AS1272	49 689 Kč	01-09-2020	unknown	rear left	v levo v zadu	Dacia
7AS1332	64 765 Kč	02-09-2019	Animal crossing	front right	vpředu vpravo	Peugeot
7AS1332	41 910 Kč	31-03-2021	Crashed	all around	všude okolo	Peugeot
7AS3144	5 496 Kč	23-07-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AS3144	133 165 Kč	22-09-2021	Crashed	front side	přední strana	Skoda
7AS3144	6 681 Kč	01-12-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda

7AS3144	6 681 Kč	20-09-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AS3144	29 800 Kč	05-10-2023	unknown	front left	vpředu vlevo	Skoda
7AS3145	19 316 Kč	26-11-2021	Damage caused by stones	front windscreen	čelní sklo	Ford
7AS3145	16 684 Kč	19-10-2022	Damage caused by stones	front windscreen	čelní sklo	Ford
7AS3550	5 168 Kč	01-01-2022	Rodent	cabling	kabeláž	Skoda
7AS3550	59 200 Kč	19-12-2022	Crashed	engine damage	poškození motoru	Skoda
7AS3550	1 200 Kč	10-10-2023	Rodent	cabling	kabeláž	Skoda
7AS4231	12 306 Kč	15-12-2021	Crashed	front left	vpředu vlevo	Volkswagen
7AS4231	0 Kč	08-07-2023	Crashed	front right	vpředu vpravo	Volkswagen
7AS4231	80 758 Kč	08-07-2023	Crashed	front right	vpředu vpravo	Volkswagen
7AS5905	0 Kč	05-10-2020	Crashed	front side	přední strana	Skoda
7AS5905	0 Kč	01-06-2023	Crashed	front side	přední strana	Skoda
7AS6609	1 500 Kč	18-02-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AS6609	0 Kč	19-09-2023	Crashed	rear left	v levo v zadu	Skoda
7AS6609	6 681 Kč	26-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AS8836	9 733 Kč	18-08-2020	Crashed	rear left	v levo v zadu	Skoda
7AS8836	19 860 Kč	30-07-2021	Crashed	front bumper	přední nárazník	Skoda
7AS8836	5 927 Kč	15-10-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AS8836	0 Kč	26-03-2024	Crashed	rear side	JohnDee s.r.o.	2019043062
7AT5418	11 218 Kč	02-02-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AT5490	26 795 Kč	14-01-2021	Crashed	rear left	v levo v zadu	Skoda
7AT5490	6 268 Kč	11-08-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AT5490	10 727 Kč	23-05-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AT7253	0 Kč	18-09-2019	Crashed	front side	přední strana	Peugeot
7AT7253	0 Kč	18-09-2019	Crashed	front side	přední strana	Peugeot
7AT7253	18 864 Kč	26-11-2019	Crashed	rear side	zadní strana	Peugeot
7AT7253	12 986 Kč	04-10-2021	unknown	damage to interior	poškození interiéru	Peugeot
7AT7253	39 610 Kč	14-05-2022	Crashed	all around	všude okolo	Peugeot
7AT7253	64 583 Kč	06-01-2023	Crashed	left side	levá strana	Peugeot
7AT7253	14 374 Kč	02-11-2023	Damage caused by stones	front windscreen	čelní sklo	Peugeot
7AT7253	21 509 Kč	15-11-2023	Crashed	rear left	v levo v zadu	Peugeot
7AU3763	15 747 Kč	23-02-2020	Crashed	front left	vpředu vlevo	Skoda
7AU3763	1 558 Kč	31-03-2022	Rodent	cabling	kabeláž	Skoda
7AU5803	0 Kč	11-10-2019	Crashed	left side	levá strana	Skoda
7AU5803	57 092 Kč	11-10-2019	Crashed	left side	levá strana	Skoda
7AU5803	81 159 Kč	26-03-2020	Vandalism	tyre	pneumatika	Skoda

7AU5803	2 Kč	22-07-2022	Crashed	front right	vpředu vpravo	Skoda
7AU5803	6 682 Kč	20-06-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AU5803	30 000 Kč	06-10-2023	Crashed	front side	přední strana	Skoda
7AU5803	20 000 Kč	27-10-2023	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
7AU5803	12 000 Kč	15-11-2023	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
7AU5829	18 065 Kč	31-10-2019	Crashed	rear bumper	zadní nárazník	Hyundai
7AU5829	45 273 Kč	26-06-2020	Crashed	right side	pravá strana	Hyundai
7AU5829	9 355 Kč	23-05-2022	Damage caused by stones	front windscreen	čelní sklo	Hyundai
7AU5829	0 Kč	31-01-2024	unknown	roof	střecha	Hyundai
7AU5829	0 Kč	05-02-2024	Crashed	rear side	zadní strana	Hyundai
7AU5829	10 992 Kč	07-02-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
7AU5829	0 Kč	19-02-2024	unknown	rear right door	pravé zadní dveře	Hyundai
7AU5830	27 710 Kč	03-07-2023	Crashed	front left	vpředu vlevo	Hyundai
7AU5830	18 637 Kč	12-09-2023	Crashed	rear side	zadní strana	Hyundai
7AU5830	1 500 Kč	13-02-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
7AU5892	0 Kč	06-02-2020	Crashed	front right	vpředu vpravo	Skoda
7AU5892	6 293 Kč	06-02-2020	Crashed	front right	vpředu vpravo	Skoda
7AU5892	0 Kč	21-06-2021	Crashed	front right	vpředu vpravo	Skoda
7AU5892	60 880 Kč	21-06-2021	Crashed	front right	vpředu vpravo	Skoda
7AU5892	41 694 Kč	10-07-2023	Crashed	front left	vpředu vlevo	Skoda
7AU5892	0 Kč	06-12-2023	Crashed	front left	vpředu vlevo	Skoda
7AU6120	54 366 Kč	26-07-2023	Crashed	front side	přední strana	Skoda
7AU6120	27 647 Kč	27-07-2023	unknown	rear right	v pravo v zadu	Skoda
7AV3947	92 604 Kč	14-12-2020	Crashed	front right	vpředu vpravo	Renault
7AV3947	0 Kč	03-01-2024	Crashed	all around	všude okolo	Renault
7AV4055	7 136 Kč	17-01-2022	unknown	right wing mirror	pravé křídlo zrcadlo	Renault
7AV4055	0 Kč	17-02-2023	Crashed	rear side	zadní strana	Renault
7AV4055	0 Kč	17-02-2023	unknown	rear right	v pravo v zadu	Renault
7AV4055	12 533 Kč	17-02-2023	Crashed	rear right	v pravo v zadu	Renault
7AV4055	6 562 Kč	09-10-2023	Damage caused by stones	front windscreen	čelní sklo	Renault
7AV4055	1 500 Kč	26-02-2024	Damage caused by stones	front windscreen	čelní sklo	Renault
7AV4055	27 345 Kč	11-03-2024	unknown	right side	pravá strana	Renault
7AV4331	10 010 Kč	10-07-2020	Inspection	left side	levá strana	Renault
7AV4331	9 507 Kč	10-07-2020	Inspection	right side	pravá strana	Renault
7AV4331	1 229 Kč	12-02-2024	Crashed	right wing mirror	pravé křídlo zrcadlo	Renault
7AV4414	0 Kč	25-03-2024	unknown	front side	Autopark Kyjov s.r.o.	2019183033
7AV8464	30 964 Kč	02-03-2023	Crashed	front side	přední strana	Skoda
7AV8464	16 912 Kč	13-03-2023	Crashed	rear side	zadní strana	Skoda

7AX1202	12 917 Kč	01-08-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AX1202	0 Kč	12-03-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AX4616	2 055 Kč	14-04-2021	Crashed	rear right	v pravo v zadu	Skoda
7AX6498	33 837 Kč	21-12-2022	Crashed	front side	přední strana	Ford
7AX6498	0 Kč	07-03-2024	Crashed	wheel housing	skříň kola	Ford
7AY1376	1 500 Kč	07-12-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY1377	14 483 Kč	02-06-2020	Crashed	front side	přední strana	Skoda
7AY1377	0 Kč	06-11-2023	Damage caused by stones	front windscreen	Tetracon Group s.r.o.	2019190011
7AY1377	0 Kč	18-03-2024	Crashed	rear door left	HAVEX-auto s.r.o.	2019190011
7AY1475	0 Kč	29-10-2020	Crashed	front side	přední strana	Skoda
7AY1475	8 061 Kč	29-10-2020	Crashed	front side	přední strana	Skoda
7AY1475	15 263 Kč	03-05-2021	unknown	right side	pravá strana	Skoda
7AY1475	7 205 Kč	17-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY1475	5 791 Kč	25-05-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY1475	6 681 Kč	03-07-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY1475	15 723 Kč	02-08-2023	Crashed	right side	pravá strana	Skoda
7AY1475	20 393 Kč	05-10-2023	Crashed	right threshold	pravý práh	Skoda
7AY1475	20 162 Kč	07-10-2023	Crashed	front right	vpředu vpravo	Skoda
7AY1475	6 488 Kč	09-10-2023	Crashed	right wing mirror	pravé křídlo zrcadlo	Skoda
7AY1475	26 307 Kč	18-10-2023	Crashed	left side	levá strana	Skoda
7AY1475	0 Kč	06-02-2024	unknown	damage to interior	poškození interiéru	Skoda
7AY2180	5 496 Kč	21-08-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY2180	0 Kč	02-08-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY2180	7 000 Kč	03-11-2023	Crashed	front door left	přední dveře vlevo	Skoda
7AY2180	10 000 Kč	03-11-2023	unknown	rear right	v pravo v zadu	Skoda
7AY2180	8 165 Kč	08-12-2023	Crashed	rear right	v pravo v zadu	Skoda
7AY3788	7 039 Kč	03-11-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY3788	9 686 Kč	09-02-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY3836	25 070 Kč	07-09-2020	Crashed	front side	přední strana	Skoda
7AY3836	0 Kč	07-09-2020	Crashed	right side	pravá strana	Skoda
7AY3836	11 699 Kč	26-06-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY4721	55 559 Kč	08-04-2022	Crashed	rear side	zadní strana	Skoda

7AY4767	8 699 Kč	03-01-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY4767	0 Kč	26-03-2024	Damage caused by stones	front windscreen	Autosklo Roger, s.r.o.	2019217112
7AY5402	0 Kč	25-01-2023	unknown	all around	všude okolo	Skoda
7AY5402	6 681 Kč	01-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY5402	33 388 Kč	01-02-2024	unknown	all around	všude okolo	Skoda
7AY6345	17 271 Kč	29-07-2020	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AY6345	7 218 Kč	04-01-2021	Crashed	wing mirror left	levé zrcátko	Volkswagen
7AY6345	0 Kč	15-12-2021	Crashed	no damage/unknown	žádné poškození / neznámé	Volkswagen
7AY6345	59 345 Kč	26-09-2022	Crashed	right side	pravá strana	Volkswagen
7AY6345	0 Kč	28-03-2023	Crashed	wing mirror left	levé zrcátko	Volkswagen
7AY6345	0 Kč	18-12-2023	Crashed	left side	levá strana	Volkswagen
7AY6489	6 268 Kč	24-03-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY6489	0 Kč	09-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY6593	17 061 Kč	26-08-2021	Crashed	left side	levá strana	Skoda
7AY6593	30 649 Kč	25-12-2022	Animal crossing	front left	vpředu vlevo	Skoda
7AY6593	76 899 Kč	23-05-2023	Nature forces	hail damage	krupobití	Skoda
7AY6593	19 789 Kč	09-08-2023	Crashed	rear side	zadní strana	Skoda
7AY6593	0 Kč	23-08-2023	Nature forces	roof	střecha	Skoda
7AY6593	5 473 Kč	10-10-2023	Crashed	rear left	v levo v zadu	Skoda
7AY6593	30 000 Kč	26-01-2024	Crashed	rear side	zadní strana	Skoda
7AY6593	21 751 Kč	26-01-2024	Crashed	front left	vpředu vlevo	Skoda
7AY6766	6 940 Kč	19-07-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY6766	8 077 Kč	14-03-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AY6766	0 Kč	15-03-2024	Crashed	rear side	zadní strana	Skoda
7AY6766	0 Kč	19-03-2024	Crashed	impact strap(s)	AUTO BÁRTA s.r.o.	2019247060
7AZ0542	40 191 Kč	15-07-2020	Crashed	rear right door	pravé zadní dveře	Volvo
7AZ0542	23 957 Kč	27-11-2023	Damage caused by stones	front windscreen	čelní sklo	Volvo
7AZ0542	39 242 Kč	15-12-2023	Crashed	front bumper	přední nárazník	Volvo
7AZ0542	35 483 Kč	15-12-2023	Crashed	rear bumper	zadní nárazník	Volvo
7AZ0542	23 635 Kč	15-12-2023	Crashed	rear right door	pravé zadní dveře	Volvo
7AZ0576	5 000 Kč	04-03-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda

7AZ0576	3 050 Kč	19-03-2021	Crashed	wing mirror left	levé zrcátko	Skoda
7AZ0576	14 711 Kč	29-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AZ0587	37 814 Kč	22-03-2022	unknown	right side	pravá strana	Skoda
7AZ0587	1 100 Kč	20-10-2022	Rodent	cabling	kabeláž	Skoda
7AZ0587	9 450 Kč	27-10-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AZ0634	24 348 Kč	07-07-2021	Crashed	rear left	v levo v zadu	Skoda
7AZ0634	1 500 Kč	23-07-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AZ0634	1 500 Kč	03-09-2021	Crashed	front windscreen	čelní sklo	Skoda
7AZ0634	39 361 Kč	09-05-2023	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
7AZ0634	0 Kč	15-12-2023	Crashed	rear right	v pravo v zadu	Skoda
7AZ0634	0 Kč	03-01-2024	Crashed	left side	levá strana	Skoda
7AZ0634	0 Kč	05-01-2024	Crashed	front right door	pravé přední dveře	Skoda
7AZ0634	0 Kč	01-02-2024	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
7AZ0656	9 311 Kč	16-03-2023	Crashed	front side	přední strana	Skoda
7AZ0656	8 586 Kč	21-09-2023	Crashed	rear bumper	zadní nárazník	Skoda
7AZ0656	8 674 Kč	01-11-2023	Crashed	rear right door	pravé zadní dveře	Skoda
7AZ0738	1 500 Kč	26-03-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
7AZ0738	34 595 Kč	09-07-2021	Crashed	front right	vpředu vpravo	Skoda
7AZ0875	8 307 Kč	04-05-2020	Damage caused by stones	front windscreen	čelní sklo	Ford
7AZ0875	104 118 Kč	11-04-2023	Crashed	rear side	zadní strana	Ford
7AZ0875	0 Kč	11-04-2023	Crashed	rear right	v pravo v zadu	Ford
7AZ6503	28 325 Kč	01-05-2020	Crashed	rear left	v levo v zadu	Toyota
7AZ6503	31 629 Kč	02-09-2020	Crashed	front left	vpředu vlevo	Toyota
7AZ6503	24 864 Kč	11-05-2021	Crashed	front left	vpředu vlevo	Toyota
7AZ6503	44 247 Kč	21-02-2022	Crashed	rear left	v levo v zadu	Toyota
7AZ6503	9 989 Kč	05-04-2022	unknown	rear right	v pravo v zadu	Toyota
7AZ6503	0 Kč	03-10-2022	Crashed	left side	levá strana	Toyota
7AZ6503	10 020 Kč	19-06-2023	Damage caused by stones	front windscreen	čelní sklo	Toyota
7AZ6503	8 306 Kč	24-10-2023	Crashed	rear side	zadní strana	Toyota
7AZ6503	10 852 Kč	31-10-2023	Crashed	front side	přední strana	Toyota
7AZ6503	0 Kč	27-11-2023	Crashed	rear left	v levo v zadu	Toyota
7AZ6503	33 708 Kč	27-11-2023	Crashed	rear left	v levo v zadu	Toyota
7AZ6751	64 643 Kč	24-07-2020	Animal crossing	front side	přední strana	Skoda
7AZ7814	10 000 Kč	03-11-2023	Crashed	rear right	v pravo v zadu	Skoda
7AZ7815	0 Kč	07-12-2023	Nature forces	roof	střecha	Skoda
7AZ7815	7 460 Kč	06-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda

7AZ9071	18 117 Kč	29-04-2021	Damage caused by stones	front windscreen	čelní sklo	Audi
7AZ9071	12 744 Kč	27-02-2023	Damage caused by stones	front windscreen	čelní sklo	Audi
7AZ9071	0 Kč	31-12-2023	Crashed	right side	pravá strana	Audi
7AZ9071	0 Kč	09-01-2024	Crashed	front right	vpředu vpravo	Audi
7AZ9071	0 Kč	09-01-2024	Crashed	right side	pravá strana	Audi
7AZ9071	0 Kč	01-02-2024	Crashed	rear side	zadní strana	Audi
7AZ9071	0 Kč	23-02-2024	Crashed	left side	levá strana	Audi
7AZ9071	0 Kč	29-02-2024	unknown	front side	přední strana	Audi
7AZ9071	0 Kč	09-03-2024	Damage caused by stones	front windscreen	čelní sklo	Audi
7AZ9071	0 Kč	18-03-2024	Crashed	front side	přední strana	Audi
7AZ9071	0 Kč	18-03-2024	Crashed	front side	1CAR, s.r.o.	2019219061
7AZ9896	13 490 Kč	04-04-2020	Stones damage several	front windscreen	čelní sklo	Volkswagen
7AZ9896	0 Kč	20-09-2021	Crashed	rear side	zadní strana	Volkswagen
7AZ9896	33 997 Kč	20-09-2021	Crashed	rear side	zadní strana	Volkswagen
7AZ9896	8 874 Kč	03-05-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
7AZ9896	20 000 Kč	04-03-2024	unknown	front side	OLFIN CAR S.R.O.	2019289006
7AZ9896	30 000 Kč	07-03-2024	Crashed	rear side	OLFIN CAR S.R.O.	2019289006
8AA1175	11 236 Kč	23-06-2021	Crashed	rear left	v levo v zadu	Skoda
8AA1175	23 539 Kč	19-05-2022	Crashed	rear bumper	zadní nárazník	Skoda
8AA1175	0 Kč	07-11-2022	Crashed	rear right	v pravo v zadu	Skoda
8AA1175	21 429 Kč	07-11-2022	Crashed	rear right	v pravo v zadu	Skoda
8AA1216	4 831 Kč	23-04-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1216	24 364 Kč	20-07-2022	Crashed	rear left	v levo v zadu	Skoda
8AA1391	1 500 Kč	31-12-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1391	0 Kč	01-10-2022	Crashed	rear side	zadní strana	Skoda
8AA1391	4 071 Kč	23-01-2024	Crashed	rear left	v levo v zadu	Skoda
8AA1391	42 096 Kč	23-01-2024	Crashed	rear side	zadní strana	Skoda
8AA1411	5 514 Kč	26-07-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1411	20 281 Kč	21-10-2023	Crashed	rear right	v pravo v zadu	Skoda
8AA1411	31 056 Kč	16-11-2023	Crashed	front left	vpředu vlevo	Skoda
8AA1431	7 203 Kč	11-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1431	13 338 Kč	01-12-2021	unknown	right threshold	pravý práh	Skoda
8AA1431	5 484 Kč	10-12-2021	unknown	front bumper	přední nárazník	Skoda
8AA1431	7 604 Kč	05-04-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1431	8 077 Kč	03-05-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda

8AA1431	0 Kč	13-12-2023	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
8AA1431	0 Kč	08-01-2024	unknown	front side	přední strana	Skoda
8AA1431	0 Kč	19-02-2024	unknown	damage to interior	poškození interiéru	Skoda
8AA1431	0 Kč	23-02-2024	unknown	rear right	v pravo v zadu	Skoda
8AA1431	0 Kč	24-02-2024	unknown	rear side	zadní strana	Skoda
8AA1432	6 150 Kč	11-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1432	0 Kč	15-01-2024	unknown	front side	přední strana	Skoda
8AA1432	0 Kč	22-02-2024	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
8AA1432	0 Kč	22-02-2024	unknown	rear side	zadní strana	Skoda
8AA1646	16 181 Kč	30-04-2021	Crashed	rear left	v levo v zadu	Skoda
8AA1646	20 204 Kč	17-06-2022	unknown	front left	vpředu vlevo	Skoda
8AA1646	7 863 Kč	19-04-2023	Crashed	rear bumper	zadní nárazník	Skoda
8AA1670	0 Kč	28-08-2021	Crashed	front bumper	přední nárazník	Skoda
8AA1751	0 Kč	12-10-2020	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
8AA1751	0 Kč	10-03-2022	Crashed	front side	přední strana	Skoda
8AA1751	54 595 Kč	10-03-2022	Crashed	front side	přední strana	Skoda
8AA1751	7 604 Kč	27-04-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1751	39 227 Kč	22-07-2022	Crashed	rear right door	pravé zadní dveře	Skoda
8AA1751	8 077 Kč	15-05-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA1751	11 525 Kč	22-02-2024	Crashed	rear left	v levo v zadu	Skoda
8AA2205	1 395 Kč	05-07-2022	Rodent	cabling	kabeláž	Skoda
8AA2205	1 500 Kč	08-03-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA2205	51 865 Kč	05-05-2023	Crashed	left side	levá strana	Skoda
8AA2205	6 681 Kč	09-05-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA2205	1 500 Kč	26-07-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA2283	11 477 Kč	11-05-2022	Crashed	front right door	pravé přední dveře	Skoda
8AA2283	0 Kč	11-05-2022	Crashed	front right door	pravé přední dveře	Skoda
8AA2283	0 Kč	31-07-2023	Crashed	all around	všude okolo	Skoda
8AA3293	38 675 Kč	18-08-2020	Crashed	front right door	pravé přední dveře	Toyota
8AA3293	25 775 Kč	15-11-2022	Crashed	rear bumper	zadní nárazník	Toyota
8AA3293	16 285 Kč	01-01-2023	Crashed	rear right	v pravo v zadu	Toyota
8AA3293	0 Kč	01-07-2023	Crashed	rear right	v pravo v zadu	Toyota
8AA3293	1 500 Kč	06-02-2024	Damage caused by stones	front windscreen	čelní sklo	Toyota
8AA5414	6 024 Kč	12-05-2021	Crashed	wing mirror left	levé zrcátko	Skoda

8AA5414	6 965 Kč	03-01-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA5414	1 500 Kč	17-06-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA5494	15 995 Kč	12-02-2021	unknown	rear bumper	zadní nárazník	Skoda
8AA5494	19 303 Kč	14-10-2021	Crashed	rear bumper	zadní nárazník	Skoda
8AA5494	5 940 Kč	16-12-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA5494	166 308 Kč	25-10-2022	Crashed	right side	pravá strana	Skoda
8AA5494	7 948 Kč	04-03-2024	Crashed	rear right door	pravé zadní dveře	Skoda
8AA5494	27 639 Kč	04-03-2024	unknown	front side	přední strana	Skoda
8AA5495	7 024 Kč	10-01-2024	Crashed	rear right	v pravo v zadu	Skoda
8AA5495	1 100 Kč	07-02-2024	unknown	roof	střecha	Skoda
8AA5513	6 389 Kč	26-01-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA5513	0 Kč	22-02-2024	Crashed	all around	všude okolo	Skoda
8AA5513	0 Kč	26-02-2024	unknown	all around	všude okolo	Skoda
8AA5515	17 921 Kč	09-03-2021	Crashed	front bumper	přední nárazník	Skoda
8AA5515	0 Kč	01-04-2021	Crashed	right threshold	pravý práh	Skoda
8AA5515	7 974 Kč	23-04-2021	Crashed	front door left	přední dveře vlevo	Skoda
8AA5515	1 740 Kč	21-05-2021	Crashed	rear door left	zadní dveře vlevo	Skoda
8AA5515	6 882 Kč	06-06-2021	unknown	right threshold	pravý práh	Skoda
8AA5515	3 163 Kč	19-07-2021	Crashed	front right door	pravé přední dveře	Skoda
8AA5515	13 219 Kč	25-05-2023	Vandalism	front right	vpředu vpravo	Skoda
8AA5515	0 Kč	06-11-2023	unknown	rear left	v levo v zadu	Skoda
8AA5515	0 Kč	16-12-2023	Crashed	right side	pravá strana	Skoda
8AA5515	0 Kč	04-01-2024	unknown	right threshold	pravý práh	Skoda
8AA5515	0 Kč	09-01-2024	Crashed	rear side	zadní strana	Skoda
8AA5515	0 Kč	01-02-2024	Crashed	front side	přední strana	Skoda
8AA5515	0 Kč	07-02-2024	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
8AA5744	8 433 Kč	18-03-2021	Crashed	rear right	v pravo v zadu	Skoda
8AA5744	7 809 Kč	27-09-2023	Crashed	rear right	v pravo v zadu	Skoda
8AA6028	6 778 Kč	14-07-2021	unknown	right wing mirror	pravé křídlo zrcadlo	Skoda
8AA6029	31 637 Kč	26-07-2023	Animal crossing	front left	vpředu vlevo	Skoda
8AA6029	0 Kč	30-12-2023	Vandalism	all around	všude okolo	Skoda
8AA6212	0 Kč	05-02-2024	unknown	bonnet	kapota	Skoda
8AA6212	0 Kč	07-02-2024	unknown	rear door left	zadní dveře vlevo	Skoda
8AA6212	0 Kč	15-02-2024	unknown	damage to interior	poškození interiéru	Skoda
8AA6302	0 Kč	03-02-2022	Crashed	no damage/unknown	žádné poškození / neznámé	Ford
8AA6302	7 415 Kč	04-12-2023	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Ford

8AA6302	15 318 Kč	19-12-2023	unknown	all around	všude okolo	Ford
8AA6302	11 857 Kč	04-01-2024	Crashed	left side	levá strana	Ford
8AA6302	22 808 Kč	04-01-2024	unknown	all around	všude okolo	Ford
8AA6302	24 298 Kč	10-01-2024	Crashed	rear side	zadní strana	Ford
8AA6302	24 341 Kč	15-01-2024	Crashed	right side	pravá strana	Ford
8AA6302	1 500 Kč	12-02-2024	Damage caused by stones	front windscreen	čelní sklo	Ford
8AA6458	11 853 Kč	30-03-2022	Crashed	rear right	v pravo v zadu	Skoda
8AA6458	4 682 Kč	31-05-2022	Crashed	wheel housing	skříň kola	Skoda
8AA6458	6 208 Kč	11-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA6499	7 000 Kč	22-01-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA6499	4 479 Kč	17-08-2022	Crashed	right side	pravá strana	Skoda
8AA6499	26 816 Kč	08-01-2024	unknown	rear right door	pravé zadní dveře	Skoda
8AA6940	5 227 Kč	24-11-2021	Damage caused by stones	front windscreen	čelní sklo	Toyota
8AA6940	0 Kč	14-03-2024	Crashed	roof	střecha	Toyota
8AA6941	0 Kč	27-03-2024	Crashed	roof	Auto Radlák, s.r.o.	2019176080
8AA6941	0 Kč	27-03-2024	Crashed	rear side	Auto Radlák, s.r.o.	2019176080
8AA7689	1 159 Kč	12-11-2021	unknown	cabling	kabeláž	Skoda
8AA7689	1 500 Kč	20-03-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AA9468	67 619 Kč	27-02-2023	Animal crossing	front side	přední strana	Skoda
8AB0348	29 032 Kč	11-11-2022	Crashed	front side	přední strana	Skoda
8AB0348	4 254 Kč	21-12-2023	Crashed	rear left	v levo v zadu	Skoda
8AB0348	4 643 Kč	03-01-2024	unknown	rear side	zadní strana	Skoda
8AB0348	1 618 Kč	08-01-2024	unknown	rear side	zadní strana	Skoda
8AB0407	1 500 Kč	10-03-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB0407	10 580 Kč	21-08-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB0407	40 465 Kč	22-08-2023	Nature forces	hail damage	krupobití	Skoda
8AB0540	34 521 Kč	01-03-2022	Animal crossing	front side	přední strana	Skoda
8AB0540	0 Kč	20-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB0540	0 Kč	22-01-2024	Crashed	front side	přední strana	Skoda
8AB0609	30 985 Kč	03-02-2020	Crashed	front door left	přední dveře vlevo	Skoda
8AB0609	7 725 Kč	26-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB0671	106 275 Kč	20-05-2021	Crashed	all around	všude okolo	Skoda
8AB0671	7 085 Kč	15-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB0671	10 200 Kč	09-02-2024	unknown	right side	pravá strana	Skoda
8AB1817	0 Kč	23-09-2023	Crashed	front right	vpředu vpravo	Skoda

8AB1917	6 075 Kč	06-04-2020	Parking damage	rear right	v pravo v zadu	Skoda
8AB1917	1 500 Kč	09-10-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB1942	20 328 Kč	15-06-2021	Crashed	rear bumper	zadní nárazník	Skoda
8AB1942	28 787 Kč	31-03-2022	Crashed	front bumper	přední nárazník	Skoda
8AB1942	13 141 Kč	30-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2126	10 157 Kč	08-10-2021	unknown	right wing mirror	pravé křídlo zrcadlo	Peugeot
8AB2126	11 477 Kč	31-01-2023	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AB2126	1 500 Kč	18-09-2023	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AB2126	12 447 Kč	16-02-2024	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AB2659	5 496 Kč	04-02-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2659	1 500 Kč	18-03-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2659	1 500 Kč	11-10-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2679	11 978 Kč	17-08-2020	Vandalism	bonnet	kapota	Skoda
8AB2679	234 197 Kč	22-06-2021	Crashed	all around	všude okolo	Skoda
8AB2679	10 516 Kč	31-05-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2679	11 450 Kč	06-04-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2679	11 450 Kč	22-06-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2679	11 450 Kč	20-07-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2727	7 059 Kč	04-09-2021	unknown	rear side	zadní strana	Skoda
8AB2727	22 916 Kč	01-09-2023	Crashed	front side	přední strana	Skoda
8AB2727	16 668 Kč	22-09-2023	unknown	rear side	zadní strana	Skoda
8AB2727	10 000 Kč	13-02-2024	unknown	bonnet	kapota	Skoda
8AB2727	8 000 Kč	15-02-2024	unknown	front side	přední strana	Skoda
8AB2728	5 496 Kč	07-07-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2728	16 474 Kč	01-03-2023	unknown	front right	vpředu vpravo	Skoda
8AB2728	10 581 Kč	03-08-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2728	76 378 Kč	23-08-2023	Animal crossing	front side	přední strana	Skoda
8AB2728	12 000 Kč	10-01-2024	Crashed	rear side	zadní strana	Skoda
8AB2728	10 294 Kč	25-01-2024	Crashed	front windscreen	čelní sklo	Skoda

8AB2728	0 Kč	25-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB2729	0 Kč	01-06-2020	Crashed	all around	všude okolo	Volkswagen
8AB2729	197 762 Kč	01-06-2020	Crashed	all around	všude okolo	Volkswagen
8AB2729	27 055 Kč	02-07-2021	Crashed	rear side	zadní strana	Volkswagen
8AB2729	3 168 Kč	24-11-2021	Rodent	cabling	kabeláž	Volkswagen
8AB2729	27 035 Kč	24-02-2022	Crashed	rear right	v pravo v zadu	Volkswagen
8AB2729	16 405 Kč	09-05-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AB2729	14 921 Kč	29-06-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AB2729	1 678 Kč	21-09-2022	Rodent	cabling	kabeláž	Volkswagen
8AB2729	1 800 Kč	30-01-2023	Rodent	cabling	kabeláž	Volkswagen
8AB2729	0 Kč	14-03-2023	Crashed	rear side	zadní strana	Volkswagen
8AB2729	0 Kč	14-03-2023	Crashed	rear side	zadní strana	Volkswagen
8AB2729	0 Kč	11-03-2024	Damage caused by stones	front windscreen	AG Experts s.r.o.	2019288011
8AB2729	0 Kč	11-03-2024	unknown	all around	Ing. Jiřina Barchánková	2019288011
8AB2834	5 998 Kč	17-06-2020	Vandalism	front right door	pravé přední dveře	Peugeot
8AB4326	27 224 Kč	09-01-2024	Crashed	all around	všude okolo	Volkswagen
8AB4370	10 991 Kč	16-11-2023	unknown	left side	levá strana	Skoda
8AB4370	7 283 Kč	30-11-2023	Crashed	front side	přední strana	Skoda
8AB4370	1 045 Kč	30-11-2023	unknown	rear side	zadní strana	Skoda
8AB4461	5 752 Kč	10-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB4461	2 Kč	15-08-2022	Crashed	rear side	zadní strana	Skoda
8AB4461	22 481 Kč	26-08-2022	Crashed	rear side	zadní strana	Skoda
8AB4461	0 Kč	10-11-2022	Crashed	front side	přední strana	Skoda
8AB4559	1 500 Kč	22-06-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB4559	1 967 Kč	10-03-2022	Rodent	cabling	kabeláž	Skoda
8AB4559	1 500 Kč	29-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB4559	12 780 Kč	24-04-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB4604	0 Kč	02-05-2022	Crashed	left side	levá strana	Skoda
8AB4604	195 899 Kč	02-05-2022	Crashed	left side	levá strana	Skoda
8AB4604	132 337 Kč	10-12-2022	Animal crossing	front side	přední strana	Skoda
8AB4604	27 954 Kč	30-01-2023	Crashed	rear bumper	zadní nárazník	Skoda
8AB4895	47 022 Kč	05-11-2022	Animal crossing	front side	přední strana	Skoda
8AB4895	6 411 Kč	02-04-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB5864	5 030 Kč	11-03-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda

8AB5864	7 876 Kč	09-05-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB5864	27 842 Kč	05-01-2023	Animal crossing	front side	přední strana	Skoda
8AB6012	6 682 Kč	12-01-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB6012	10 149 Kč	01-10-2023	Crashed	rear left	v levo v zadu	Skoda
8AB6012	7 336 Kč	31-10-2023	Crashed	rear side	zadní strana	Skoda
8AB6155	0 Kč	06-02-2024	Crashed	front side	přední strana	Skoda
8AB6684	19 155 Kč	17-03-2022	Crashed	rear bumper	zadní nárazník	Skoda
8AB7452	9 500 Kč	16-11-2020	Crashed	front left	vpředu vlevo	Skoda
8AB7452	2 797 Kč	20-05-2023	Vandalism	side window	boční okno	Skoda
8AB7452	16 405 Kč	13-08-2023	Vandalism	break-in	vloupání	Skoda
8AB7452	11 675 Kč	30-10-2023	Crashed	rear side	zadní strana	Skoda
8AB7452	7 114 Kč	10-11-2023	Crashed	right side	pravá strana	Skoda
8AB7452	7 167 Kč	10-11-2023	Crashed	right threshold	pravý práh	Skoda
8AB7452	34 809 Kč	04-12-2023	Crashed	front left	vpředu vlevo	Skoda
8AB7452	12 276 Kč	08-01-2024	Crashed	front side	přední strana	Skoda
8AB7915	0 Kč	26-04-2020	Crashed	rear right	v pravo v zadu	Volkswagen
8AB7915	25 669 Kč	26-04-2020	Crashed	rear right	v pravo v zadu	Volkswagen
8AB7915	35 449 Kč	31-07-2020	Animal crossing	front side	přední strana	Volkswagen
8AB7915	66 654 Kč	26-06-2022	Crashed	rear left	v levo v zadu	Volkswagen
8AB7915	0 Kč	01-03-2024	Crashed	right side	pravá strana	Volkswagen
8AB7915	0 Kč	12-03-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AB8009	0 Kč	25-11-2020	Crashed	front side	přední strana	Volkswagen
8AB8009	64 091 Kč	25-11-2020	Crashed	front side	přední strana	Volkswagen
8AB8009	34 300 Kč	04-01-2024	Crashed	all around	všude okolo	Volkswagen
8AB9573	12 508 Kč	01-04-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB9573	24 097 Kč	26-09-2022	Crashed	front right	vpředu vpravo	Skoda
8AB9573	0 Kč	26-09-2022	unknown	front right	vpředu vpravo	Skoda
8AB9573	12 702 Kč	27-10-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AB9573	1 503 Kč	27-12-2022	Rodent	cabling	kabeláž	Skoda
8AB9573	2 268 Kč	30-01-2024	Rodent	cabling	kabeláž	Skoda
8AB9573	0 Kč	30-01-2024	unknown	cabling	kabeláž	Skoda
8AB9573	1 500 Kč	01-03-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AC1160	38 517 Kč	07-02-2021	Damage caused by stones	front windscreen	čelní sklo	BMW
8AC1160	0 Kč	09-03-2024	Damage caused by stones	front windscreen	CARTEC PRAHA S.R.O.	2019282008
8AC1762	31 033 Kč	10-02-2021	Crashed	rear right	v pravo v zadu	Volkswagen
8AC1762	12 049 Kč	20-06-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen

8AC1762	0 Kč	24-10-2023	Crashed	left side	levá strana	Volkswagen
8AC1762	0 Kč	10-01-2024	Crashed	front side	přední strana	Volkswagen
8AC1762	0 Kč	10-01-2024	Crashed	front side	přední strana	Volkswagen
8AC1762	0 Kč	20-02-2024	Crashed	front left	vpředu vlevo	Volkswagen
8AC1762	0 Kč	21-02-2024	unknown	front right door	pravé přední dveře	Volkswagen
8AC1944	0 Kč	15-09-2020	Crashed	no damage/unknown	žádné poškození / neznámé	Ford
8AC1944	81 179 Kč	07-04-2022	Crashed	front side	přední strana	Ford
8AC1944	25 733 Kč	16-02-2023	Vandalism	left side	levá strana	Ford
8AC1944	20 392 Kč	18-09-2023	Crashed	front side	přední strana	Ford
8AC1944	28 221 Kč	16-01-2024	Crashed	rear side	zadní strana	Ford
8AC1950	0 Kč	13-03-2022	Rodent	cabling	kabeláž	Hyundai
8AC1950	18 369 Kč	12-12-2023	Crashed	rear right door	pravé zadní dveře	Hyundai
8AC2061	15 355 Kč	02-10-2021	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Peugeot
8AC2061	3 100 Kč	24-01-2022	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AC2338	5 551 Kč	02-07-2020	Damage caused by stones	front right door	pravé přední dveře	Skoda
8AC2338	18 551 Kč	09-06-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AC2340	24 314 Kč	18-10-2021	Crashed	front right	vpředu vpravo	Skoda
8AC2340	10 879 Kč	22-10-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AC4252	63 507 Kč	28-01-2021	Crashed	rear side	zadní strana	Skoda
8AC4252	0 Kč	22-01-2024	Crashed	left side	levá strana	Skoda
8AC4252	0 Kč	22-01-2024	Crashed	left side	levá strana	Skoda
8AC4252	8 500 Kč	01-03-2024	Crashed	right side	pravá strana	Skoda
8AC4252	0 Kč	26-03-2024	Damage caused by stones	front windscreen	AG Experts s.r.o.	2020050015
8AC4253	63 068 Kč	22-05-2023	Crashed	rear side	zadní strana	Skoda
8AC5812	0 Kč	08-01-2024	Crashed	right side	pravá strana	Ford
8AC5812	0 Kč	01-03-2024	Crashed	rear left	v levo v zadu	Ford
8AC5812	0 Kč	01-03-2024	Crashed	front side	přední strana	Ford
8AC5812	0 Kč	04-03-2024	unknown	rear left	v levo v zadu	Ford
8AC5812	0 Kč	04-03-2024	Crashed	front right	vpředu vpravo	Ford
8AC5932	9 825 Kč	04-04-2022	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AC5932	22 617 Kč	10-05-2022	Crashed	all around	všude okolo	Peugeot
8AC5932	0 Kč	10-05-2022	unknown	all around	všude okolo	Peugeot
8AC5932	0 Kč	10-05-2022	Crashed	no damage/unknown	žádné poškození / neznámé	Peugeot
8AC5932	153 013 Kč	10-06-2022	Crashed	left side	levá strana	Peugeot
8AC5932	11 478 Kč	30-03-2023	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AC5932	0 Kč	21-10-2023	Crashed	front left	vpředu vlevo	Peugeot
8AC5932	190 000 Kč	21-10-2023	Crashed	front left	vpředu vlevo	Peugeot

8AC6653	9 058 Kč	16-12-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AC6653	51 622 Kč	21-07-2021	Crashed	right side	pravá strana	Skoda
8AC6653	7 798 Kč	12-11-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AC6653	28 058 Kč	03-01-2023	Animal crossing	front left	vpředu vlevo	Skoda
8AC6653	0 Kč	05-03-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AC7077	6 911 Kč	01-02-2024	unknown	rear side	zadní strana	Ford
8AC7793	42 372 Kč	16-02-2021	Crashed	left side	levá strana	Mazda
8AC7793	12 341 Kč	26-10-2021	Damage caused by stones	front windscreen	čelní sklo	Mazda
8AC7793	1 500 Kč	27-02-2024	Damage caused by stones	front windscreen	čelní sklo	Mazda
8AC7794	26 925 Kč	27-04-2020	Drove backwards	front bumper	přední nárazník	Hyundai
8AC7794	0 Kč	28-12-2023	Crashed	right side	pravá strana	Hyundai
8AC7794	0 Kč	07-02-2024	Crashed	rear left	v levo v zadu	Hyundai
8AC9336	10 729 Kč	04-09-2020	Crashed	wing mirror left	levé zrcátko	Toyota
8AC9336	109 928 Kč	08-02-2021	Crashed	rear right	v pravo v zadu	Toyota
8AC9336	0 Kč	08-02-2021	Crashed	rear right	v pravo v zadu	Toyota
8AC9336	2 Kč	03-11-2021	Crashed	right side	pravá strana	Toyota
8AC9336	10 270 Kč	11-01-2024	Damage caused by stones	front windscreen	čelní sklo	Toyota
8AC9336	42 000 Kč	06-02-2024	Crashed	all around	všude okolo	Toyota
8AD0239	1 500 Kč	04-04-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AD0239	10 536 Kč	22-12-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AD1554	18 239 Kč	16-05-2020	Crashed	front/rear damage	poškození zepředu / zezadu	Skoda
8AD1554	0 Kč	26-10-2020	Crashed	right side	pravá strana	Skoda
8AD1554	0 Kč	26-10-2020	Crashed	right side	pravá strana	Skoda
8AD1554	89 217 Kč	21-12-2021	Crashed	front left	vpředu vlevo	Skoda
8AD1554	0 Kč	21-12-2021	Crashed	front left	vpředu vlevo	Skoda
8AD1554	10 516 Kč	11-06-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AD1554	0 Kč	19-08-2023	Crashed	front left	vpředu vlevo	Skoda
8AD1825	24 540 Kč	05-10-2021	Crashed	rear side	zadní strana	Skoda
8AD4850	3 399 Kč	28-11-2022	Crashed	front right	vpředu vpravo	Skoda
8AD4850	11 767 Kč	01-12-2022	Crashed	rear left	v levo v zadu	Skoda
8AD4850	46 432 Kč	01-12-2022	unknown	front right door	pravé přední dveře	Skoda
8AD4850	13 518 Kč	05-12-2022	Crashed	rear right	v pravo v zadu	Skoda
8AD4850	5 846 Kč	12-12-2022	Crashed	front left	vpředu vlevo	Skoda
8AD5210	37 886 Kč	06-02-2022	Crashed	right threshold	pravý práh	Skoda
8AD6618	72 488 Kč	12-03-2023	Crashed	front side	přední strana	Volkswagen

8AD6618	12 917 Kč	03-01-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AD6618	0 Kč	10-03-2024	Animal crossing	rear right	v pravo v zadu	Volkswagen
8AD6959	57 470 Kč	14-05-2021	Crashed	rear side	zadní strana	Renault
8AD6959	8 945 Kč	14-09-2022	Damage caused by stones	front windscreen	čelní sklo	Renault
8AD7235	21 716 Kč	29-06-2022	Nature forces	hail damage	krupobití	Skoda
8AD7238	6 916 Kč	04-09-2020	Crashed	rear left	v levo v zadu	Skoda
8AD7238	1 500 Kč	26-04-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AD7238	6 916 Kč	16-02-2023	Crashed	front right	vpředu vpravo	Skoda
8AD7238	6 411 Kč	17-05-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AD7337	2 Kč	22-03-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AD9636	5 280 Kč	19-02-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AD9636	30 645 Kč	05-10-2021	Crashed	right side	pravá strana	Skoda
8AE0066	17 825 Kč	12-09-2022	Crashed	rear right	v pravo v zadu	Skoda
8AE1203	8 785 Kč	10-06-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AE1203	34 035 Kč	14-12-2022	Crashed	left side	levá strana	Volkswagen
8AE1203	0 Kč	18-09-2023	Rodent	cabling	kabeláž	Volkswagen
8AE1203	1 500 Kč	02-02-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AE1471	76 671 Kč	30-01-2021	Crashed	front right	vpředu vpravo	Toyota
8AE1508	23 129 Kč	10-11-2022	Crashed	front side	přední strana	Mercedes-Benz
8AE1508	8 862 Kč	15-01-2023	Crashed	front side	přední strana	Mercedes-Benz
8AE1740	19 490 Kč	23-02-2021	Damage caused by stones	front windscreen	čelní sklo	Toyota
8AE1821	5 497 Kč	01-09-2020	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AE1821	9 901 Kč	17-09-2021	Crashed	rear bumper	zadní nárazník	Skoda
8AE1821	16 702 Kč	11-12-2023	Crashed	front left	vpředu vlevo	Skoda
8AE3075	33 209 Kč	18-09-2020	Animal crossing	front side	přední strana	Skoda
8AE3075	7 371 Kč	08-03-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AE3075	62 919 Kč	01-07-2021	Animal crossing	front side	přední strana	Skoda
8AE3075	19 955 Kč	12-10-2022	Animal crossing	front side	přední strana	Skoda
8AE3075	8 454 Kč	17-05-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AE3075	8 431 Kč	19-09-2023	unknown	front side	přední strana	Skoda
8AE3075	0 Kč	10-10-2023	Crashed	left side	levá strana	Skoda
8AE3075	23 978 Kč	16-01-2024	unknown	rear left	v levo v zadu	Skoda

8AE7691	14 085 Kč	03-07-2020	Crashed	front left	vpředu vlevo	Volkswagen
8AE7691	1 500 Kč	02-05-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AE7691	9 233 Kč	15-10-2022	Crashed	rear door left	zadní dveře vlevo	Volkswagen
8AE7691	9 465 Kč	18-10-2022	unknown	rear left	v levo v zadu	Volkswagen
8AE7691	20 000 Kč	10-11-2022	Crashed	rear bumper	zadní nárazník	Volkswagen
8AE7691	31 523 Kč	15-11-2022	unknown	front left	vpředu vlevo	Volkswagen
8AE7691	2 006 Kč	03-01-2023	Rodent	cabling	kabeláž	Volkswagen
8AE7732	8 378 Kč	01-07-2020	Crashed	front bumper	přední nárazník	Skoda
8AE7732	45 366 Kč	07-09-2020	Theft	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
8AE7732	7 421 Kč	29-03-2021	unknown	rear side	zadní strana	Skoda
8AE7732	19 426 Kč	22-07-2022	Crashed	rear side	zadní strana	Skoda
8AE7732	13 818 Kč	21-09-2023	unknown	rear left	v levo v zadu	Skoda
8AE7732	8 659 Kč	25-10-2023	unknown	front side	přední strana	Skoda
8AE7732	14 278 Kč	12-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AE8077	10 193 Kč	21-10-2021	Nature forces	left side	levá strana	Skoda
8AE8077	2 638 Kč	29-11-2021	Rodent	cabling	kabeláž	Skoda
8AE8077	1 523 Kč	28-02-2023	Rodent	cabling	kabeláž	Skoda
8AE8077	11 011 Kč	13-08-2023	Crashed	rear right	v pravo v zadu	Skoda
8AE8928	11 994 Kč	03-02-2021	unknown	right side	pravá strana	Skoda
8AE8928	25 593 Kč	08-02-2021	Inspection	rear bumper	zadní nárazník	Skoda
8AE8928	8 728 Kč	11-05-2021	unknown	front side	přední strana	Skoda
8AE9531	34 038 Kč	22-08-2021	Crashed	rear side	zadní strana	Skoda
8AE9531	1 500 Kč	20-01-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AE9531	49 982 Kč	31-08-2023	Crashed	rear side	zadní strana	Skoda
8AF0081	1 288 Kč	18-09-2021	Crashed	wing mirror left	levé zrcátko	Volkswagen
8AF0081	13 846 Kč	17-03-2022	unknown	all around	všude okolo	Volkswagen
8AF0265	9 051 Kč	01-07-2021	Crashed	threshold left	práh vlevo	Volkswagen
8AF0265	9 080 Kč	04-10-2022	Crashed	front right	vpředu vpravo	Volkswagen
8AF0265	7 752 Kč	12-06-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AF0265	15 000 Kč	12-10-2023	Crashed	front right	vpředu vpravo	Volkswagen
8AF3077	31 860 Kč	13-12-2020	Animal crossing	front side	přední strana	Skoda
8AF3077	9 391 Kč	07-04-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AF3077	0 Kč	20-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AF3192	10 981 Kč	09-05-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AF3192	30 913 Kč	08-02-2023	Crashed	bonnet	kapota	Skoda
8AF3192	14 250 Kč	13-02-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda

8AF3192	0 Kč	18-03-2024	unknown	front side	přední strana	Skoda
8AF3262	821 Kč	26-08-2020	Crashed	front side	přední strana	Skoda
8AF3262	32 123 Kč	29-04-2021	Crashed	right side	pravá strana	Skoda
8AF3262	13 914 Kč	30-08-2021	Crashed	front left	vpředu vlevo	Skoda
8AF3262	0 Kč	21-10-2022	Crashed	no damage/unknown	žádné poškození / neznámé	Skoda
8AF3262	8 538 Kč	14-03-2024	unknown	rear side	zadní strana	Skoda
8AF8634	90 169 Kč	07-08-2022	Crashed	right side	pravá strana	Audi
8AF8634	24 324 Kč	05-05-2023	Damage caused by stones	front windscreen	čelní sklo	Audi
8AF8634	21 999 Kč	05-05-2023	Crashed	rear side	zadní strana	Audi
8AF8634	8 749 Kč	19-08-2023	Crashed	front side	přední strana	Audi
8AH0160	9 927 Kč	30-11-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AH1897	2 074 Kč	29-06-2021	Crashed	right wing mirror	pravé křídlo zrcadlo	Toyota
8AH1897	46 631 Kč	19-01-2023	Crashed	front right	vpředu vpravo	Toyota
8AH1897	75 000 Kč	21-12-2023	unknown	all around	všude okolo	Toyota
8AH2145	1 500 Kč	28-04-2021	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AH2145	16 696 Kč	20-05-2021	unknown	front left	vpředu vlevo	Volkswagen
8AH2145	8 518 Kč	20-10-2021	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AH2145	0 Kč	01-11-2022	Crashed	front right	vpředu vpravo	Volkswagen
8AH2145	21 802 Kč	01-11-2022	Crashed	right side	pravá strana	Volkswagen
8AH2145	0 Kč	25-01-2023	Crashed	left side	levá strana	Volkswagen
8AH2145	87 035 Kč	25-01-2023	Crashed	left side	levá strana	Volkswagen
8AH5681	10 437 Kč	22-06-2023	Crashed	front right	vpředu vpravo	Volkswagen
8AH5963	0 Kč	25-04-2023	Crashed	front right	vpředu vpravo	Volkswagen
8AH5963	16 645 Kč	25-04-2023	Crashed	front right	vpředu vpravo	Volkswagen
8AH5963	6 942 Kč	09-02-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AH5965	6 802 Kč	01-07-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AH5965	6 809 Kč	28-09-2022	unknown	left and right side	levá a pravá strana	Volkswagen
8AH5965	2 551 Kč	26-04-2023	Rodent	cabling	kabeláž	Volkswagen
8AH5965	16 864 Kč	08-01-2024	Crashed	left side	levá strana	Volkswagen
8AH5965	16 353 Kč	05-02-2024	Crashed	front side	přední strana	Volkswagen
8AH5993	10 695 Kč	19-08-2021	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AH5993	67 653 Kč	06-09-2021	Crashed	rear side	zadní strana	Peugeot
8AH6079	9 777 Kč	13-07-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AH6079	404 803 Kč	29-04-2023	Crashed	rear side	zadní strana	Volkswagen
8AH6079	1 500 Kč	13-02-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen

8AH8837	6 149 Kč	19-07-2021	Damage caused by stones	front windscreen	čelní sklo	Renault
8AH8837	0 Kč	02-10-2023	unknown	damage to interior	poškození interiéru	Renault
8AH8837	7 499 Kč	14-03-2024	Damage caused by stones	front windscreen	čelní sklo	Renault
8AH8840	14 576 Kč	12-01-2022	Vandalism	left side	levá strana	Skoda
8AH8978	9 894 Kč	10-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AH8978	9 534 Kč	24-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AH8978	20 559 Kč	14-10-2021	Crashed	rear bumper	zadní nárazník	Skoda
8AH8978	10 175 Kč	08-11-2021	unknown	right side	pravá strana	Skoda
8AH8980	10 534 Kč	10-09-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AH8980	25 246 Kč	15-08-2022	Crashed	rear side	zadní strana	Skoda
8AH8980	11 001 Kč	15-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AH8980	13 196 Kč	17-04-2023	Rodent	cabling	kabeláž	Skoda
8AI4173	104 762 Kč	26-03-2021	Crashed	right side	pravá strana	Toyota
8AI5093	45 530 Kč	29-11-2021	Crashed	front right	vpředu vpravo	Skoda
8AI5093	2 217 Kč	17-09-2022	Rodent	cabling	kabeláž	Skoda
8AI5093	1 500 Kč	08-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI5093	1 630 Kč	11-08-2023	unknown	cabling	kabeláž	Skoda
8AI5093	9 118 Kč	01-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI5093	33 076 Kč	11-12-2023	Crashed	all around	všude okolo	Skoda
8AI6366	64 098 Kč	05-08-2021	Crashed	right side	pravá strana	Volkswagen
8AI6366	7 227 Kč	11-02-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AI6366	0 Kč	29-06-2022	Crashed	rear right	v pravo v zadu	Volkswagen
8AI6366	0 Kč	01-03-2024	unknown	left side	levá strana	Volkswagen
8AI6366	0 Kč	21-03-2024	Crashed	rear right	PORSCHE INTER AUTO CZ SPOL.	2020077027
8AI6569	78 280 Kč	09-11-2020	Crashed	rear side	zadní strana	Skoda
8AI6569	9 534 Kč	25-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI6569	16 826 Kč	31-10-2021	Crashed	engine cover	kryt motoru	Skoda
8AI6569	1 500 Kč	19-04-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI6569	15 631 Kč	17-08-2023	unknown	front left	vpředu vlevo	Skoda
8AI6569	35 451 Kč	14-09-2023	unknown	front side	přední strana	Skoda
8AI6569	28 817 Kč	11-12-2023	unknown	rear side	zadní strana	Skoda
8AI6569	16 884 Kč	08-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI7342	11 867 Kč	22-04-2021	Crashed	front left	vpředu vlevo	Skoda

8AI7342	8 334 Kč	01-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI7342	11 163 Kč	07-02-2023	Crashed	rear right	v pravo v zadu	Skoda
8AI7342	8 616 Kč	03-10-2023	Crashed	front side	přední strana	Skoda
8AI7342	20 190 Kč	14-11-2023	unknown	front side	přední strana	Skoda
8AI7342	14 337 Kč	12-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI8189	1 366 Kč	04-09-2021	Rodent	cabling	kabeláž	Skoda
8AI8189	7 460 Kč	29-03-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI8189	7 460 Kč	10-10-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI8189	13 624 Kč	12-02-2024	unknown	rear right	v pravo v zadu	Skoda
8AI8189	0 Kč	18-03-2024	Crashed	rear left	Luboš Maruškevič	2020164031
8AI8189	0 Kč	19-03-2024	Damage caused by stones	front windscreen	AG Experts s.r.o.	2020164031
8AI9006	7 909 Kč	07-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AI9006	0 Kč	22-03-2024	Damage caused by stones	front windscreen	AG Experts s.r.o.	2020146031
8AI9525	1 500 Kč	11-01-2024	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AJ2483	62 998 Kč	26-01-2021	Crashed	front side	přední strana	Peugeot
8AJ2483	16 825 Kč	24-06-2021	Crashed	rear left	v levo v zadu	Peugeot
8AJ2483	43 745 Kč	20-08-2021	unknown	rear side	zadní strana	Peugeot
8AJ2483	0 Kč	18-07-2022	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Peugeot
8AJ2590	0 Kč	19-12-2022	Crashed	front right	vpředu vpravo	Skoda
8AJ2590	0 Kč	19-12-2022	Crashed	front right	vpředu vpravo	Skoda
8AJ2590	6 600 Kč	03-11-2023	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
8AJ2590	0 Kč	14-12-2023	Animal crossing	front side	přední strana	Skoda
8AJ2590	0 Kč	13-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AJ4575	9 116 Kč	21-02-2022	unknown	rear door left	zadní dveře vlevo	Skoda
8AJ4575	50 485 Kč	26-11-2022	Crashed	front side	přední strana	Skoda
8AJ6174	18 777 Kč	14-07-2023	Animal crossing	rear left	v levo v zadu	Toyota
8AJ6174	9 922 Kč	05-02-2024	Crashed	front bumper	přední nárazník	Toyota
8AJ6189	34 432 Kč	05-11-2021	Animal crossing	front side	přední strana	Skoda
8AJ6189	25 159 Kč	22-07-2022	Crashed	front left	vpředu vlevo	Skoda
8AJ6310	0 Kč	15-02-2024	Crashed	right side	pravá strana	Toyota
8AJ6473	81 684 Kč	28-01-2021	Crashed	left side	levá strana	Skoda
8AJ6473	48 162 Kč	30-04-2021	Crashed	rear side	zadní strana	Skoda
8AJ6473	13 604 Kč	04-12-2023	Crashed	rear left	v levo v zadu	Skoda
8AJ6473	8 638 Kč	07-12-2023	unknown	left side	levá strana	Skoda
8AJ6473	9 902 Kč	08-12-2023	Crashed	front side	přední strana	Skoda

8AJ6520	0 Kč	29-07-2021	Crashed	front right door	pravé přední dveře	Skoda
8AJ6520	11 754 Kč	29-07-2021	Crashed	right side	pravá strana	Skoda
8AJ6520	13 199 Kč	01-09-2022	Crashed	rear right	v pravo v zadu	Skoda
8AJ6520	18 339 Kč	11-12-2023	Crashed	front side	přední strana	Skoda
8AJ6520	0 Kč	19-03-2024	Crashed	front side	přední strana	Skoda
8AJ7996	702 Kč	15-02-2021	Crashed	all around	všude okolo	Volkswagen
8AJ7996	1 500 Kč	11-09-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AJ8994	7 437 Kč	15-02-2021	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AJ8994	35 470 Kč	30-03-2022	Crashed	front right	vpředu vpravo	Peugeot
8AJ8994	99 694 Kč	01-09-2022	Crashed	front side	přední strana	Peugeot
8AJ9285	32 296 Kč	02-08-2023	Crashed	rear left	v levo v zadu	Skoda
8AJ9285	10 745 Kč	09-11-2023	Crashed	front side	přední strana	Skoda
8AK1574	0 Kč	16-10-2020	Crashed	front side	přední strana	Skoda
8AK1574	123 677 Kč	16-10-2020	Crashed	front side	přední strana	Skoda
8AK1574	78 373 Kč	01-11-2022	Animal crossing	front side	přední strana	Skoda
8AK1574	8 883 Kč	04-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK1698	35 225 Kč	26-04-2022	Crashed	front right	vpředu vpravo	Volkswagen
8AK1698	7 874 Kč	13-06-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AK1703	0 Kč	14-11-2023	Crashed	all around	všude okolo	Ford
8AK2159	8 040 Kč	22-03-2022	unknown	bonnet	kapota	Toyota
8AK2159	14 474 Kč	22-03-2022	unknown	front bumper	přední nárazník	Toyota
8AK2159	40 414 Kč	22-04-2022	Crashed	front right	vpředu vpravo	Toyota
8AK2159	8 892 Kč	26-06-2022	Crashed	rear left	v levo v zadu	Toyota
8AK2159	31 851 Kč	27-06-2022	unknown	tyre and/or rim	pneumatika a / nebo ráfek	Toyota
8AK2159	137 874 Kč	14-10-2023	Crashed	rear side	zadní strana	Toyota
8AK2159	20 000 Kč	01-01-2024	Nature forces	all around	všude okolo	Toyota
8AK2159	9 430 Kč	17-01-2024	Crashed	rear left	v levo v zadu	Toyota
8AK2159	1 710 Kč	17-01-2024	Crashed	front side	přední strana	Toyota
8AK2238	507 Kč	21-03-2022	Rodent	front side	přední strana	Skoda
8AK2238	0 Kč	31-08-2022	Crashed	rear bumper	zadní nárazník	Skoda
8AK2238	8 093 Kč	31-08-2022	Crashed	rear bumper	zadní nárazník	Skoda
8AK2238	10 195 Kč	02-09-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK2256	0 Kč	04-08-2021	Crashed	rear side	zadní strana	Skoda
8AK2256	28 637 Kč	04-08-2021	Crashed	rear side	zadní strana	Skoda
8AK2256	8 404 Kč	24-08-2021	Crashed	front bumper	přední nárazník	Skoda
8AK2256	0 Kč	19-10-2023	Crashed	front side	přední strana	Skoda
8AK2256	0 Kč	08-11-2023	Crashed	rear side	zadní strana	Skoda
8AK2256	0 Kč	16-01-2024	Crashed	right side	pravá strana	Skoda
8AK2258	8 127 Kč	13-07-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda

8AK2258	8 656 Kč	13-04-2023	Crashed	rear left	v levo v zadu	Skoda
8AK5721	7 639 Kč	07-01-2021	Rodent	cabling	kabeláž	Peugeot
8AK5721	15 856 Kč	20-10-2022	Crashed	front right	vpředu vpravo	Peugeot
8AK5721	13 286 Kč	16-08-2023	unknown	right wing mirror	pravé křídlo zrcadlo	Peugeot
8AK5721	0 Kč	16-08-2023	unknown	right wing mirror	pravé křídlo zrcadlo	Peugeot
8AK5721	34 549 Kč	15-11-2023	unknown	rear right	v pravo v zadu	Peugeot
8AK5721	0 Kč	15-11-2023	unknown	rear right	v pravo v zadu	Peugeot
8AK5721	13 699 Kč	09-01-2024	unknown	rear side	zadní strana	Peugeot
8AK6358	10 534 Kč	08-12-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK6358	11 110 Kč	10-03-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK6358	21 150 Kč	20-04-2022	Crashed	front left	vpředu vlevo	Skoda
8AK6358	12 674 Kč	08-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK6358	12 674 Kč	19-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK7583	75 683 Kč	28-03-2023	Crashed	rear left	v levo v zadu	Skoda
8AK7583	0 Kč	28-03-2023	Crashed	rear left	v levo v zadu	Skoda
8AK7583	5 927 Kč	30-05-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK7583	1 500 Kč	06-03-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK7617	40 700 Kč	08-09-2021	Crashed	rear side	zadní strana	Skoda
8AK8570	7 127 Kč	10-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AK8570	11 016 Kč	08-11-2023	Crashed	rear side	zadní strana	Skoda
8AK8603	2 300 Kč	03-06-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AK8603	0 Kč	19-07-2022	Crashed	no damage/unknown	žádné poškození / neznámé	Volkswagen
8AK8603	7 669 Kč	01-08-2022	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AK8603	8 221 Kč	14-03-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AK8603	13 061 Kč	13-10-2023	unknown	rear left	v levo v zadu	Volkswagen
8AK8603	5 669 Kč	12-12-2023	unknown	right threshold	pravý práh	Volkswagen
8AK8603	1 500 Kč	13-12-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AK8603	21 162 Kč	08-01-2024	unknown	front right	vpředu vpravo	Volkswagen
8AK8603	16 234 Kč	08-01-2024	unknown	rear side	zadní strana	Volkswagen
8AK8603	15 218 Kč	10-01-2024	Crashed	rear right	v pravo v zadu	Volkswagen
8AK9318	16 880 Kč	08-12-2023	Crashed	right threshold	pravý práh	Peugeot
8AK9318	8 765 Kč	11-03-2024	Damage caused by stones	front windscreen	čelní sklo	Peugeot

8AL0230	8 971 Kč	09-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AL0876	36 062 Kč	09-08-2022	Crashed	front right	vpředu vpravo	Skoda
8AL0876	27 479 Kč	11-11-2022	Crashed	rear right	v pravo v zadu	Skoda
8AL0876	0 Kč	01-03-2023	Crashed	rear right	v pravo v zadu	Skoda
8AL0876	0 Kč	01-03-2023	Crashed	rear right	v pravo v zadu	Skoda
8AL0876	1 500 Kč	19-04-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AL0876	11 870 Kč	05-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AL3357	3 000 Kč	22-07-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AL3357	3 000 Kč	28-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AL4414	8 488 Kč	12-04-2022	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AL4414	17 976 Kč	06-02-2023	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AL4449	0 Kč	30-12-2022	Crashed	rear bumper	zadní nárazník	Toyota
8AL4449	24 247 Kč	30-12-2022	Crashed	rear bumper	zadní nárazník	Toyota
8AL4449	29 196 Kč	14-02-2024	Damage caused by stones	front windscreen	čelní sklo	Toyota
8AL8798	18 418 Kč	22-05-2022	Crashed	rear right door	pravé zadní dveře	Hyundai
8AL8798	9 626 Kč	24-06-2022	Damage caused by stones	front windscreen	čelní sklo	Hyundai
8AL8798	24 402 Kč	06-11-2023	unknown	engine cover	kryt motoru	Hyundai
8AL8798	17 307 Kč	30-01-2024	Crashed	rear side	zadní strana	Hyundai
8AL9201	29 518 Kč	02-02-2023	Crashed	rear side	zadní strana	Skoda
8AL9201	12 997 Kč	18-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AL9326	9 955 Kč	19-01-2022	Crashed	front bumper	přední nárazník	Skoda
8AL9326	603 Kč	11-04-2023	Rodent	engine cover	kryt motoru	Skoda
8AL9326	9 931 Kč	11-07-2023	Crashed	front side	přední strana	Skoda
8AL9326	10 009 Kč	17-07-2023	unknown	rear side	zadní strana	Skoda
8AL9326	7 201 Kč	06-12-2023	Crashed	threshold left	práh vlevo	Skoda
8AM1183	12 922 Kč	25-03-2022	Damage caused by stones	front windscreen	čelní sklo	Hyundai
8AM1183	30 198 Kč	24-03-2023	Crashed	rear side	zadní strana	Hyundai
8AM1203	5 361 Kč	30-05-2022	Crashed	front side	přední strana	Skoda
8AM1203	2 Kč	01-07-2022	Crashed	rear side	zadní strana	Skoda
8AM1203	26 278 Kč	05-08-2022	Crashed	right side	pravá strana	Skoda
8AM1203	38 219 Kč	15-03-2023	Crashed	rear right	v pravo v zadu	Skoda
8AM1203	6 712 Kč	14-08-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda

8AM1203	28 348 Kč	22-09-2023	Crashed	right side	pravá strana	Skoda
8AM1203	13 334 Kč	01-12-2023	Crashed	front side	přední strana	Skoda
8AM3103	10 904 Kč	07-08-2023	Crashed	rear bumper	zadní nárazník	Skoda
8AM3103	12 811 Kč	04-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AM3103	17 854 Kč	11-12-2023	Crashed	front right	vpředu vpravo	Skoda
8AM3293	42 000 Kč	17-01-2024	Crashed	rear right	v pravo v zadu	Skoda
8AM3391	5 847 Kč	07-11-2022	Crashed	front left	vpředu vlevo	Skoda
8AM4969	9 203 Kč	01-03-2021	Rodent	cabling	kabeláž	Skoda
8AM4969	9 535 Kč	16-11-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AM4969	170 983 Kč	01-05-2022	Animal crossing	front side	přední strana	Skoda
8AM4969	24 416 Kč	30-11-2023	Nature forces	hail damage	krupobití	Skoda
8AM4969	6 604 Kč	10-01-2024	unknown	front right	vpředu vpravo	Skoda
8AM4969	597 Kč	05-02-2024	Rodent	engine cover	kryt motoru	Skoda
8AM4969	0 Kč	05-02-2024	Rodent	engine cover	kryt motoru	Skoda
8AM4971	0 Kč	04-01-2023	Crashed	front side	přední strana	Skoda
8AM4971	106 798 Kč	04-01-2023	Crashed	front side	přední strana	Skoda
8AM4971	0 Kč	09-01-2024	Crashed	front side	přední strana	Skoda
8AM4971	0 Kč	13-02-2024	Crashed	rear bumper	EKAS Automotive s.r.o.	2020287019
8AM4971	0 Kč	21-02-2024	Damage caused by stones	front windscreen	EKAS Automotive s.r.o.	2020287019
8AM5473	0 Kč	05-05-2021	Crashed	left side	levá strana	Hyundai
8AM5473	0 Kč	08-02-2024	Crashed	rear right	v pravo v zadu	Hyundai
8AM5662	135 521 Kč	16-10-2023	Crashed	rear side	zadní strana	Skoda
8AM5662	16 888 Kč	15-11-2023	unknown	right side	pravá strana	Skoda
8AM5662	25 552 Kč	12-02-2024	unknown	front side	přední strana	Skoda
8AM5754	1 500 Kč	07-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AM6478	29 879 Kč	11-06-2021	Animal crossing	left side	levá strana	Volkswagen
8AM6478	149 096 Kč	30-10-2023	Crashed	front side	přední strana	Volkswagen
8AM6478	20 684 Kč	25-01-2024	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AM6516	8 803 Kč	28-08-2021	Crashed	rear bumper	zadní nárazník	Skoda
8AM6516	57 571 Kč	26-08-2023	Crashed	front side	přední strana	Skoda
8AM6516	10 287 Kč	27-10-2023	Crashed	rear left	v levo v zadu	Skoda
8AM6516	18 758 Kč	22-11-2023	Crashed	front right	vpředu vpravo	Skoda
8AM7951	12 606 Kč	27-10-2021	unknown	front side	přední strana	Skoda
8AM8705	20 000 Kč	22-08-2023	unknown	front side	přední strana	Hyundai
8AM8705	20 000 Kč	17-10-2023	Crashed	rear side	zadní strana	Hyundai
8AM8705	0 Kč	30-01-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
8AM9034	20 097 Kč	18-04-2023	Crashed	front side	přední strana	Toyota
8AM9034	0 Kč	30-11-2023	Crashed	front right	vpředu vpravo	Toyota

8AM9087	10 210 Kč	15-08-2023	Damage caused by stones	front windscreen	čelní sklo	Hyundai
8AN0815	12 148 Kč	27-06-2022	Nature forces	hail damage	krupobití	Skoda
8AN2372	17 518 Kč	25-10-2021	Damage caused by stones	front windscreen	čelní sklo	Mercedes-Benz
8AN2372	0 Kč	22-11-2022	Crashed	right wing mirror	pravé křídlo zrcadlo	Mercedes-Benz
8AN2372	17 111 Kč	22-05-2023	Animal crossing	front side	přední strana	Mercedes-Benz
8AN3603	0 Kč	07-02-2024	Crashed	rear side	zadní strana	Skoda
8AN3603	0 Kč	19-02-2024	Crashed	front side	přední strana	Skoda
8AN3921	11 084 Kč	11-01-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN3921	1 500 Kč	05-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN4268	5 280 Kč	31-05-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN4268	5 989 Kč	16-03-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN4268	1 500 Kč	29-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN6190	0 Kč	01-04-2021	Crashed	front side	přední strana	Toyota
8AN6190	166 277 Kč	01-04-2021	Crashed	front side	přední strana	Toyota
8AN6190	24 141 Kč	20-06-2022	Crashed	front side	přední strana	Toyota
8AN6190	16 259 Kč	27-06-2022	Crashed	front right door	pravé přední dveře	Toyota
8AN6190	10 270 Kč	07-02-2023	Damage caused by stones	front windscreen	čelní sklo	Toyota
8AN6190	15 426 Kč	16-02-2023	Crashed	rear right door	pravé zadní dveře	Toyota
8AN6190	12 568 Kč	10-10-2023	Crashed	rear bumper	zadní nárazník	Toyota
8AN6196	8 049 Kč	05-02-2024	Damage caused by stones	front windscreen	čelní sklo	Peugeot
8AN6196	7 369 Kč	08-02-2024	Crashed	rear right	v pravo v zadu	Peugeot
8AN6196	10 453 Kč	08-02-2024	unknown	rear left	v levo v zadu	Peugeot
8AN6215	29 589 Kč	18-05-2021	Theft	damage to interior	poškození interiéru	Skoda
8AN6215	7 747 Kč	02-09-2021	Crashed	rear bumper	zadní nárazník	Skoda
8AN6215	12 940 Kč	04-04-2022	unknown	right threshold	pravý práh	Skoda
8AN6215	5 811 Kč	11-04-2023	Crashed	front bumper	přední nárazník	Skoda
8AN6215	16 170 Kč	01-08-2023	Crashed	right side	pravá strana	Skoda
8AN7287	9 894 Kč	29-04-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN7287	0 Kč	18-05-2021	Rodent	cabling	kabeláž	Skoda
8AN7287	12 810 Kč	19-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN7287	0 Kč	27-02-2024	Crashed	front side	přední strana	Skoda

8AN7287	0 Kč	27-02-2024	unknown	rear left	v levo v zadu	Skoda
8AN7884	17 212 Kč	28-11-2022	Crashed	right side	pravá strana	Toyota
8AN7884	8 645 Kč	14-03-2023	Animal crossing	wing mirror left	levé zrcátko	Toyota
8AN7884	12 638 Kč	08-01-2024	Crashed	rear right	v pravo v zadu	Toyota
8AN7884	9 136 Kč	26-02-2024	Crashed	threshold left	práh vlevo	Toyota
8AN8780	20 857 Kč	07-02-2022	unknown	front side	přední strana	Skoda
8AN9022	5 514 Kč	23-05-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN9022	32 904 Kč	24-08-2023	Crashed	front side	přední strana	Skoda
8AN9022	0 Kč	20-09-2023	Crashed	front left	vpředu vlevo	Skoda
8AN9022	6 583 Kč	25-10-2023	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
8AN9022	17 936 Kč	14-11-2023	Crashed	rear side	zadní strana	Skoda
8AN9051	1 500 Kč	11-08-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AN9051	0 Kč	01-08-2023	Crashed	rear left	v levo v zadu	Skoda
8AN9051	34 234 Kč	01-08-2023	Crashed	rear left	v levo v zadu	Skoda
8AN9828	14 458 Kč	09-02-2023	Damage caused by stones	front windscreen	čelní sklo	Toyota
8AP3588	60 064 Kč	18-02-2022	Crashed	rear bumper	zadní nárazník	Skoda
8AP4263	10 981 Kč	08-09-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AP4263	0 Kč	21-03-2024	unknown	front right door	Lak Racing s.r.o.	2020331030
8AP4686	12 631 Kč	04-11-2022	Crashed	left side	levá strana	Citroen
8AP4686	67 881 Kč	21-06-2023	Crashed	front right	vpředu vpravo	Citroen
8AP4686	0 Kč	06-11-2023	Crashed	no damage/unknown	žádné poškození / neznámé	Citroen
8AP4686	9 944 Kč	15-11-2023	Crashed	right threshold	pravý práh	Citroen
8AP4686	38 172 Kč	10-01-2024	Crashed	rear side	zadní strana	Citroen
8AP6837	0 Kč	30-01-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AP7085	0 Kč	24-06-2021	Nature forces	roof	střecha	Skoda
8AP7085	0 Kč	16-03-2023	Crashed	front left	vpředu vlevo	Skoda
8AP7085	54 449 Kč	16-03-2023	Crashed	front left	vpředu vlevo	Skoda
8AP7085	6 987 Kč	03-07-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AP7085	0 Kč	04-03-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AP7276	0 Kč	24-07-2021	Crashed	rear left	v levo v zadu	Peugeot
8AP7276	42 448 Kč	24-07-2021	Crashed	rear left	v levo v zadu	Peugeot
8AP7276	18 059 Kč	18-01-2022	Crashed	rear right	v pravo v zadu	Peugeot
8AP9299	20 659 Kč	22-05-2023	Crashed	left side	levá strana	Skoda
8AP9299	11 352 Kč	30-06-2023	Crashed	rear left	v levo v zadu	Skoda
8AP9299	0 Kč	12-09-2023	Crashed	front right door	pravé přední dveře	Skoda
8AP9299	13 378 Kč	29-02-2024	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda

8AR0145	9 387 Kč	05-05-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AR0145	2 Kč	25-07-2022	unknown	right side	pravá strana	Skoda
8AR0145	10 293 Kč	12-01-2023	Crashed	front bumper	přední nárazník	Skoda
8AR1102	25 000 Kč	22-11-2021	unknown	front right	vpředu vpravo	Skoda
8AR1102	111 929 Kč	14-01-2023	Crashed	left side	levá strana	Skoda
8AR2547	6 874 Kč	02-11-2021	Crashed	front left	vpředu vlevo	Skoda
8AR2582	11 846 Kč	10-09-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AR2582	12 010 Kč	05-08-2022	Crashed	left side	levá strana	Skoda
8AR2582	13 457 Kč	28-12-2022	Crashed	front right door	pravé přední dveře	Skoda
8AR4342	9 237 Kč	26-09-2022	Damage caused by stones	front windscreen	čelní sklo	Audi
8AR4342	12 970 Kč	23-01-2024	Damage caused by stones	front windscreen	čelní sklo	Audi
8AR5746	0 Kč	21-04-2023	Crashed	rear left	v levo v zadu	Opel
8AR5746	0 Kč	21-04-2023	Crashed	rear left	v levo v zadu	Opel
8AS3618	5 745 Kč	11-12-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AS3620	28 182 Kč	24-11-2022	Animal crossing	front left	vpředu vlevo	Skoda
8AS3620	36 150 Kč	31-01-2023	Crashed	rear side	zadní strana	Skoda
8AS3620	1 500 Kč	02-08-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AT2070	0 Kč	08-02-2022	Crashed	front side	přední strana	Volkswagen
8AT2070	53 700 Kč	08-02-2022	Crashed	front side	přední strana	Volkswagen
8AT2070	21 000 Kč	01-10-2022	Crashed	tyre	pneumatika	Volkswagen
8AT2070	8 874 Kč	14-12-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
8AT4939	7 260 Kč	14-09-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AT4939	0 Kč	02-11-2023	Crashed	front side	přední strana	Skoda
8AU1317	16 848 Kč	11-07-2023	Crashed	rear left	v levo v zadu	Skoda
8AU1317	7 694 Kč	19-09-2023	Crashed	rear left	v levo v zadu	Skoda
8AU1317	9 459 Kč	26-10-2023	Crashed	rear side	zadní strana	Skoda
8AU1317	24 569 Kč	04-11-2023	Crashed	front side	přední strana	Skoda
8AU1317	10 209 Kč	27-11-2023	Crashed	left side	levá strana	Skoda
8AU1317	7 977 Kč	06-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AX1125	98 361 Kč	20-12-2021	Crashed	front right	vpředu vpravo	Skoda
8AX5315	0 Kč	17-02-2022	Crashed	front door left	přední dveře vlevo	Skoda
8AX5315	0 Kč	01-06-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AX5315	0 Kč	15-06-2022	Crashed	front right door	pravé přední dveře	Skoda
8AX5838	75 561 Kč	23-07-2023	Crashed	front right	vpředu vpravo	Skoda
8AY1203	13 013 Kč	12-08-2022	Vandalism	front side	přední strana	Skoda

8AY1203	0 Kč	01-11-2023	Crashed	rear right	v pravo v zadu	Skoda
8AY1203	0 Kč	12-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AY1423	1 500 Kč	05-04-2022	Damage caused by stones	front windscreen	čelní sklo	Kia
8AY1423	15 868 Kč	20-06-2023	Damage caused by stones	front windscreen	čelní sklo	Kia
8AY1426	55 000 Kč	22-01-2024	Crashed	rear side	zadní strana	Kia
8AY9601	6 987 Kč	14-03-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
8AY9601	111 537 Kč	24-10-2023	Animal crossing	front right	vpředu vpravo	Skoda
8AZ4225	0 Kč	27-02-2024	Crashed	rear door left	zadní dveře vlevo	Opel
8AZ5313	60 673 Kč	20-01-2022	Crashed	right side	pravá strana	Skoda
8AZ5313	5 089 Kč	02-05-2023	Vandalism	front right	vpředu vpravo	Skoda
9AA6797	59 492 Kč	29-06-2022	Nature forces	hail damage	krupobití	Hyundai
9AA6797	12 000 Kč	22-02-2024	Crashed	rear side	zadní strana	Hyundai
9AA9827	1 500 Kč	01-03-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AB1774	78 759 Kč	01-12-2022	Crashed	all around	všude okolo	Skoda
9AB1774	12 810 Kč	22-02-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
9AB1774	0 Kč	22-02-2024	unknown	rear side	zadní strana	Skoda
9AB1789	9 244 Kč	04-03-2022	Crashed	rear bumper	zadní nárazník	Skoda
9AB1789	10 111 Kč	06-04-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
9AB1789	12 444 Kč	22-06-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
9AB1789	1 500 Kč	01-08-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
9AB3360	25 903 Kč	21-03-2022	Crashed	rear right	v pravo v zadu	Hyundai
9AB3360	45 514 Kč	08-12-2022	Crashed	rear side	zadní strana	Hyundai
9AB3360	10 210 Kč	08-01-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AB3360	35 088 Kč	09-01-2024	Crashed	rear side	zadní strana	Hyundai
9AB3360	15 647 Kč	09-01-2024	unknown	front side	přední strana	Hyundai
9AB3361	8 172 Kč	09-01-2024	Crashed	front side	přední strana	Hyundai
9AB3361	10 210 Kč	17-01-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AB3362	8 602 Kč	13-04-2022	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AB3362	10 210 Kč	06-02-2023	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AB3362	7 997 Kč	22-01-2024	Crashed	rear left	v levo v zadu	Hyundai
9AB3365	10 135 Kč	19-07-2022	Crashed	rear right	v pravo v zadu	Hyundai
9AB3365	48 622 Kč	02-12-2022	Crashed	rear right	v pravo v zadu	Hyundai

9AB3365	0 Kč	12-01-2023	Crashed	rear side	zadní strana	Hyundai
9AB3365	40 484 Kč	12-01-2023	Crashed	rear bumper	zadní nárazník	Hyundai
9AB3365	27 255 Kč	25-01-2024	Crashed	front side	přední strana	Hyundai
9AB3365	14 681 Kč	25-01-2024	Crashed	rear side	zadní strana	Hyundai
9AB4226	115 553 Kč	17-04-2022	Animal crossing	all around	všude okolo	Skoda
9AB4226	0 Kč	17-03-2023	Crashed	front left	vpředu vlevo	Skoda
9AB4226	20 470 Kč	17-03-2023	Crashed	front left	vpředu vlevo	Skoda
9AC2014	100 011 Kč	25-05-2020	Animal crossing	front side	přední strana	Volkswagen
9AC2014	0 Kč	25-05-2020	Animal crossing	front side	přední strana	Volkswagen
9AC2014	66 631 Kč	15-09-2020	Crashed	right wing mirror	pravé křídlo zrcadlo	Volkswagen
9AC2014	22 898 Kč	19-02-2021	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
9AC2014	187 479 Kč	02-02-2022	Crashed	rear side	zadní strana	Volkswagen
9AC2014	0 Kč	02-02-2022	Crashed	rear side	zadní strana	Volkswagen
9AC2014	22 764 Kč	01-03-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
9AC2014	0 Kč	21-01-2024	Crashed	right side	pravá strana	Volkswagen
9AC2127	9 584 Kč	07-09-2022	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AC2127	1 500 Kč	25-01-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AC4121	44 022 Kč	21-10-2022	Crashed	right side	pravá strana	Citroen
9AC4121	0 Kč	08-03-2024	unknown	rear side	zadní strana	Citroen
9AE1737	31 788 Kč	10-03-2023	Crashed	front left	vpředu vlevo	Kia
9AE1737	8 693 Kč	20-10-2023	Vandalism	side window	boční okno	Kia
9AE3550	0 Kč	25-08-2022	Damage caused by stones	front windscreen	čelní sklo	Kia
9AE3550	9 909 Kč	02-06-2023	Crashed	rear side	zadní strana	Kia
9AE3550	22 132 Kč	16-06-2023	Crashed	left and right side	levá a pravá strana	Kia
9AF1799	21 919 Kč	17-07-2023	unknown	rear side	zadní strana	Skoda
9AF1799	6 987 Kč	21-12-2023	Crashed	front windscreen	čelní sklo	Skoda
9AI6425	9 665 Kč	19-07-2023	unknown	front side	přední strana	Opel
9AI7854	1 500 Kč	14-03-2023	Damage caused by stones	front windscreen	čelní sklo	Opel
9AI7854	16 206 Kč	28-03-2023	Crashed	rear right door	pravé zadní dveře	Opel
9AK3110	124 882 Kč	26-11-2021	Crashed	all around	všude okolo	Hyundai
9AK3110	0 Kč	06-11-2023	unknown	front right door	pravé přední dveře	Hyundai
9AL6217	46 981 Kč	29-03-2023	Crashed	all around	všude okolo	Volkswagen
9AM9532	0 Kč	17-02-2024	Crashed	rear left	v levo v zadu	Volkswagen
9AN3377	1 500 Kč	01-02-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AP0416	0 Kč	12-05-2023	unknown	no damage/unknown	žádné poškození / neznámé	Toyota

9AP1028	28 540 Kč	28-11-2023	Crashed	rear side	zadní strana	Volkswagen
9AP1209	5 571 Kč	03-01-2024	unknown	roof	střecha	Kia
9AP1209	60 000 Kč	03-01-2024	Crashed	front left	vpředu vlevo	Kia
9AP1383	0 Kč	03-02-2023	Crashed	engine cover	kryt motoru	Toyota
9AP5612	66 141 Kč	17-02-2023	Crashed	all around	všude okolo	Toyota
9AP5613	5 342 Kč	08-03-2023	unknown	bonnet	kapota	Toyota
9AP5613	7 374 Kč	28-03-2023	Crashed	wing mirror left	levé zrcátko	Toyota
9AP5613	1 500 Kč	06-04-2023	Damage caused by stones	front windscreen	čelní sklo	Toyota
9AP5613	32 885 Kč	08-11-2023	unknown	rear right	v pravo v zadu	Toyota
9AP5613	50 751 Kč	15-11-2023	unknown	front right	vpředu vpravo	Toyota
9AP8368	0 Kč	03-07-2023	Crashed	rear left	v levo v zadu	Toyota
9AP8368	25 962 Kč	03-07-2023	Crashed	rear left	v levo v zadu	Toyota
9AP8368	0 Kč	02-03-2024	Crashed	rear side	zadní strana	Toyota
9AP8368	0 Kč	02-03-2024	Crashed	rear side	zadní strana	Toyota
9AR3501	11 743 Kč	26-02-2024	Damage caused by stones	front windscreen	čelní sklo	Hyundai
9AS0888	19 448 Kč	01-12-2023	Crashed	rear left	v levo v zadu	Cupra
9AT0237	1 500 Kč	27-12-2023	Damage caused by stones	front windscreen	čelní sklo	Volvo
9AT4750	15 458 Kč	16-06-2023	Damage caused by stones	front windscreen	čelní sklo	Toyota
9AU0367	28 419 Kč	20-11-2023	unknown	front right	vpředu vpravo	Skoda
EL012AI	8 604 Kč	08-03-2021	Damage caused by stones	front windscreen	čelní sklo	Skoda
EL012AI	1 500 Kč	15-11-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
EL111AR	29 635 Kč	15-11-2021	Crashed	front right	vpředu vpravo	Skoda
EL111AR	8 961 Kč	12-06-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
EL152AI	16 402 Kč	22-02-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
EL152AI	15 963 Kč	24-06-2023	Crashed	rear left	v levo v zadu	Skoda
EL152AI	0 Kč	05-01-2024	Damage caused by stones	front windscreen	čelní sklo	Skoda
EL174AF	24 807 Kč	21-12-2022	Crashed	rear right	v pravo v zadu	Skoda
EL216AJ	305 111 Kč	25-11-2020	Crashed	front side	přední strana	Skoda
EL216AJ	11 832 Kč	16-11-2022	Damage caused by stones	front windscreen	čelní sklo	Skoda
EL216AJ	14 418 Kč	11-12-2023	Damage caused by stones	front windscreen	čelní sklo	Skoda
EL258AK	137 544 Kč	13-04-2022	unknown	right side	pravá strana	Kia
EL258AK	14 627 Kč	06-07-2022	unknown	roof	střecha	Kia
EL304BE	32 000 Kč	23-04-2023	Damage caused by stones	roof	střecha	Tesla
EL419AJ	17 778 Kč	09-01-2024	Crashed	front left	vpředu vlevo	Volkswagen

EL510AD	0 Kč	31-01-2023	Crashed	tyre and/or rim	pneumatika a / nebo ráfek	Skoda
EL510AD	0 Kč	16-09-2023	Crashed	rear side	zadní strana	Skoda
EL510AD	0 Kč	06-10-2023	Crashed	rear side	zadní strana	Skoda
EL510AD	0 Kč	05-03-2024	Crashed	rear left	Auto Palace Západ s.r.o.	2019298026
EL510AD	0 Kč	06-03-2024	Crashed	front side	přední strana	Skoda
EL531AF	20 331 Kč	11-01-2023	Damage caused by stones	front windscreen	čelní sklo	Nissan
EL537AB	64 572 Kč	13-01-2023	Crashed	rear side	zadní strana	Volkswagen
EL537AB	183 382 Kč	03-11-2023	Th.party failed to give way	right side	pravá strana	Volkswagen
EL538AR	0 Kč	06-06-2023	Crashed	left side	levá strana	Skoda
EL538AR	0 Kč	28-08-2023	Crashed	right wing mirror	pravé křídlo zrcadlo	Skoda
EL638AR	20 517 Kč	14-05-2022	Damage caused by stones	front windscreen	čelní sklo	Hyundai
EL638AR	228 803 Kč	17-05-2022	Crashed	front side	přední strana	Hyundai
EL638AR	0 Kč	20-07-2023	Crashed	right wing mirror	pravé křídlo zrcadlo	Hyundai
EL675AI	24 131 Kč	22-11-2021	Damage caused by stones	front windscreen	čelní sklo	Tesla
EL675AI	22 832 Kč	16-12-2022	Damage caused by stones	front windscreen	čelní sklo	Tesla
EL675AI	17 540 Kč	02-01-2024	Crashed	threshold left	práh vlevo	Tesla
EL675AI	13 522 Kč	05-01-2024	Damage caused by stones	front windscreen	čelní sklo	Tesla
EL849BH	58 912 Kč	16-12-2020	Crashed	left and right side	levá a pravá strana	Volvo
EL849BH	0 Kč	19-02-2021	Crashed	right side	pravá strana	Volvo
EL849BH	193 464 Kč	19-02-2021	Crashed	right side	pravá strana	Volvo
EL849BH	27 588 Kč	17-04-2021	Damage caused by stones	front windscreen	čelní sklo	Volvo
EL849BH	16 349 Kč	30-04-2021	Crashed	front right	vpředu vpravo	Volvo
EL849BH	28 000 Kč	06-11-2023	Crashed	rear right	v pravo v zadu	Volvo
EL849BH	46 000 Kč	20-11-2023	Crashed	all around	všude okolo	Volvo
EL849BH	18 000 Kč	20-11-2023	unknown	rear side	zadní strana	Volvo
EL849BH	50 000 Kč	20-11-2023	Crashed	rear left	v levo v zadu	Volvo
EL849BH	98 000 Kč	20-11-2023	Crashed	front side	přední strana	Volvo
EL849BH	1 500 Kč	27-11-2023	Damage caused by stones	front windscreen	čelní sklo	Volvo
EL862AZ	17 422 Kč	22-06-2023	Damage caused by stones	front windscreen	čelní sklo	Volkswagen
EL884AT	0 Kč	16-05-2022	Crashed	front bumper	přední nárazník	Hyundai
EL884AT	38 402 Kč	27-05-2022	Damage caused by stones	front windscreen	čelní sklo	Hyundai
EL904BA	28 900 Kč	26-04-2023	Damage caused by stones	front windscreen	čelní sklo	Tesla

EL904BA	0 Kč	20-12-2023	Damage caused by stones	front windscreen	čelní sklo	Tesla
EL994AE	0 Kč	14-08-2021	unknown	no damage/unknown	žádné poškození / neznámé	Skoda
EL994AE	58 389 Kč	24-05-2023	Crashed	front side	přední strana	Skoda

Model
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Proace D4D128 L 1.2L2H2
Oct.Combi 1.4 CNG Amb. G-TEC
Oct.Combi 1.4 CNG Amb. G-TEC
Oct.Combi 1.4 CNG Amb. G-TEC
Oct.Combi 1.4 CNG Amb. G-TEC
Oct.Combi 1.4 CNG Amb. G-TEC
Oct.Combi 1.4 CNG Amb. G-TEC
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active

Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
Qubo 1.4 77 Active
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
TourneoCon. 1.5TDCI 74 Trnd
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Citigo 1.0 44 Active 3d
Tr.KV TDCi125 310L2 TREND F
Tr.KV TDCi125 310L2 TREND F
Tr.KV TDCi125 310L2 TREND F
Tr.KV TDCi125 310L2 TREND F
Tr.KV TDCi125 310L2 TREND F
Focus Kombi 1.5TDCI 95 Trend
Focus Kombi 1.5TDCI 95 Trend
Focus Kombi 1.5TDCI 95 Trend
Focus Kombi 1.5TDCI 95 Trend
Focus Kombi 1.5TDCI 95 Trend
Focus Kombi 1.5TDCI 95 Trend
308 SW 1.6bHDI 100k Allure S&S

308 SW 1.6bHDI 100k Allure S&S
308 SW 1.6bHDI 100k Allure S&S
308 SW 1.6bHDI 100k Allure S&S
308 SW 1.6bHDI 100k Allure S&S
308 SW 1.6bHDI 100k Allure S&S
308 SW 1.6bHDI 100k Allure S&S
Kodiaq 2.0TSl132 Ambi 4x4 DSG
Kodiaq 2.0TSl132 Ambi 4x4 DSG
Kodiaq 2.0TSl132 Ambi 4x4 DSG
Kodiaq 2.0TSl132 Ambi 4x4 DSG
Skoda
2.0bHdi130 3500 L2 4d
2.0bHdi130 3500 L2 4d
2.0bHdi130 3500 L2 4d
2.0bHdi130 3500 L2 4d
2.0bHdi130 3500 L2 4d
2.0bHdi130 3500 L2 4d
Kodiaq 2.0TDI110 Style 4x4
Kodiaq 2.0TDI110 Style 4x4
Kodiaq 2.0TDI110 Style 4x4
Kodiaq 2.0TDI110 Style 4x4
Kodiaq 2.0TDI110 Style 4x4
Kodiaq 2.0TDI110 Style 4x4
Kodiaq 2.0TDI110 Style 4x4
Mondeo Kom.2.0TDCI132 Titanium
Mondeo Kom.2.0TDCI132 Titanium
Mondeo Kom.2.0TDCI132 Titanium
Mondeo Kom.2.0TDCI132 Titanium
Mondeo Kom.2.0TDCI132 Titanium
Mondeo Kom.2.0TDCI132 Titanium
Octavia 1.6TDI85 Style
Octavia 1.6TDI85 Style
Octavia 1.6TDI85 Style
Octavia 1.6TDI85 Style
Octavia 1.6TDI85 Style
Octavia 1.6TDI85 Style
Octavia 1.6TDI85 Style
FabiaCo 1.0TSl81 Ambition

Octavia Com 1.6TDI 85 Ambit.AT
Octavia Com 1.6TDI 85 Ambit.AT
Octavia Com 1.6TDI 85 Ambit.AT
Octavia Com 1.6TDI 85 Ambit.AT
Octavia 1.0TSI 85 Ambition
Octavia 1.0TSI 85 Ambition
Octavia 1.0TSI 85 Ambition
2008 1.5BHDi 100 Allure
2008 1.5BHDi 100 Allure
2008 1.5BHDi 100 Allure
2008 1.5BHDi 100 Allure
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Pas.Var.2.0TDI 110 Com.
Pas.Var.2.0TDI 110 Com.
Pas.Var.2.0TDI 110 Com.
Pas.Var.2.0TDI 110 Com.
OctaviaCo1.5TSI 110 Style
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Kodiaq 2.0TDI 140 Amb. 4x4 AT
Kodiaq 2.0TDI 140 Amb. 4x4 AT
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
3008 1.5bHDi 130 Active
Sharan 2.0 TDI110 HL
Sharan 2.0 TDI110 HL
Sharan 2.0 TDI110 HL

Golf Var 1.5TSI EVO110 HL DSG
Golf Var 1.5TSI EVO110 HL DSG
Pas.Var.2.0TDI 140 Comf.4X4 AT
Octavia Com TDI 110 Style AT
Octavia Com TDI 110 Style AT
Octavia Com TDI 110 Style AT
Octavia Com TDI 110 Style
Fabia Com 1.0TSI 81 Ambition
Fabia Com 1.0TSI 81 Ambition
MastFu dCi130 L3H2P3 COOL
MastFu dCi130 L3H2P3 COOL
MastFu dCi130 L3H2P3 COOL
MastFu dCi130 L3H2P3 COOL
MastFu dCi130 L3H2P3 COOL
MastFu dCi130 L3H2P3 COOL
Kodiaq 2.0TSI 140 L&K 4x4 AT
Octavia 1.5TSI 110 Ambition
Octavia 1.5TSI 110 Ambition
Octavia 1.5TSI 110 Ambition
Octavia 1.5TSI 110 Ambition
Octavia 1.6TDI 85 Style
Octavia 1.6TDI 85 Style
OctaviaCo1.5TSI 110 L&K
OctaviaCo1.5TSI 110 L&K
OctaviaCo1.5TSI 110 L&K
Skoda
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
Karoq 1.6TDI 85 Style AT
Octavia 1.5TSI 110 L&K AT
Duster 1.5dCi 85 Comfort 4x4
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
Octa.Com TDI 135 Scout 4x4 AT
Octa.Com TDI 135 Scout 4x4 AT
Octa.Com TDI 135 Scout 4x4 AT

Octa.Com TDI 135 Scout 4x4 AT
Octa.Com TDI 135 Scout 4x4 AT
Mondeo Kom.2.0EB 110 Titanium
Mondeo Kom.2.0EB 110 Titanium
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Pas.Var.2.0TDI 110 HL
Octavia 2.0TDI 110 Style AT
Octavia 2.0TDI 110 Style AT
Octavia Com.TSI 85 Style
Octavia Com.TSI 85 Style
Octavia Com.TSI 85 Style
Fabia 1.0MPI 44 Active
Fabia 1.0MPI 44 Active
Fabia 1.0MPI 44 Active
Skoda
Kodiaq 2.0TSI 140 Style 4x4 AT
Superb 2.0TDI 140 Amb. 4x4 AT
Superb 2.0TDI 140 Amb. 4x4 AT
Superb 2.0TDI 140 Amb. 4x4 AT
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
2008 1.5BHDi 100 Active
Octavia Com TDI 110 L&K AT
Octavia Com TDI 110 L&K AT
Octavia 2.0TSI DSG RS
Octavia 2.0TSI DSG RS
Octavia 2.0TSI DSG RS

Octavia 2.0TSI DSG RS
Octavia 2.0TSI DSG RS
Octavia 2.0TSI DSG RS
Octavia 2.0TSI DSG RS
Octavia 2.0TSI DSG RS
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
i30 kombi 1.6CRDi 85 Tri kolor
Karoq 2.0TDI 110 Style 4x4 AT
Karoq 2.0TDI 110 Style 4x4 AT
Karoq 2.0TDI 110 Style 4x4 AT
Karoq 2.0TDI 110 Style 4x4 AT
Karoq 2.0TDI 110 Style 4x4 AT
Karoq 2.0TDI 110 Style 4x4 AT
OctaviaCo1.5TSI 110 Style
OctaviaCo1.5TSI 110 Style
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Kangoo Expr.dCi75 Cool
Skoda
Fabia 1.0TSI 70 Active
Fabia 1.0TSI 70 Active

Caddy 2.0TDI 75 TL
Caddy 2.0TDI 75 TL
Scala 1.6TDI 85 Ambition
Mondeo Kom.2.0EB 110 Titanium
Mondeo Kom.2.0EB 110 Titanium
Kodiaq 2.0TDI 110 Sportline AT
Fabia 1.0TSI 70 Ambition
Skoda
Skoda
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia 1.5TSI 110 Style AT
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Kodiaq 2.0TDI 110 Style 4x4
Kodiaq 2.0TDI 110 Style 4x4
Kodiaq 2.0TDI 110 Style 4x4
Karoq 1.6TDI 85 Ambition AT

OctaviaCo1.5TSI 110 Style AT
Skoda
Octavia Com TDI 110 Style
Octavia Com TDI 110 Style
Octavia Com TDI 110 Style
Pas. Var.2.0TDI 176 Eleg.4M AT
Pas. Var.2.0TDI 176 Eleg.4M AT
Pas. Var.2.0TDI 176 Eleg.4M AT
Pas. Var.2.0TDI 176 Eleg.4M AT
Pas. Var.2.0TDI 176 Eleg.4M AT
Pas. Var.2.0TDI 176 Eleg.4M AT
Pas. Var.2.0TDI 176 Eleg.4M AT
Supe.FL1.5TSI 110 Ambition
Supe.FL1.5TSI 110 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Style AT
Scala 1.0TSI 85 Style AT
Scala 1.0TSI 85 Style AT
Skoda
XC60 D4 Momentum AT
XC60 D4 Momentum AT
XC60 D4 Momentum AT
XC60 D4 Momentum AT
XC60 D4 Momentum AT
Kodiaq 2.0TSI 140 L&K 4x4 AT

Kodiaq 2.0TSI 140 L&K 4x4 AT
Kodiaq 2.0TSI 140 L&K 4x4 AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Supe.FL2.0TDI 110 Style
Octavia Com.TSI 85 Ambition
Octavia Com.TSI 85 Ambition
Octavia Com.TSI 85 Ambition
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Foc.Kom.1.5EBI.120 Tre.Ed.P.
Foc.Kom.1.5EBI.120 Tre.Ed.P.
Foc.Kom.1.5EBI.120 Tre.Ed.P.
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Octavia Com 1.6TDI 85 Ambition
Kodiaq 2.0TDI 176 RS 4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT

Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Q5 2.0TDI 140 qtrr sport STR
Audi
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Volkswagen
Volkswagen
Supe.FL2.0TDI 110 Ambition AT
Supe.FL2.0TDI 110 Ambition AT
Supe.FL2.0TDI 110 Ambition AT
Supe.FL2.0TDI 110 Ambition AT
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Scala 1.0TSI 85 Style
Scala 1.0TSI 85 Style
Scala 1.0TSI 85 Style
Scala 1.0TSI 85 Style
Scala 1.0TSI 85 Style

Mondeo Kom.2.0EB 110 Titanium
Mondeo Kom.2.0EB 110 Titanium
Mondeo Kom.2.0EB 110 Titanium
Mondeo Kom.2.0EB 110 Titanium
Mondeo Kom.2.0EB 110 Titanium
Mondeo Kom.2.0EB 110 Titanium
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Hilux 2.4D4D Live DC 4x4
Hilux 2.4D4D Live DC 4x4
Toyota
Toyota
Kodiaq 2.0TSI 140 L&K 4x4 AT
Kodiaq 2.0TSI 140 L&K 4x4 AT
Octavia Com TDI 110 Style
Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style
Karoq 1.5TSI 110 ACT Ambit.AT
Karoq 1.5TSI 110 ACT Ambit.AT
Karoq 1.5TSI 110 ACT Ambit.AT
Fabia Com 1.0TSI 81 Ambition
Fabia Com 1.0TSI 81 Ambition
Fabia Com 1.0TSI 81 Ambition
Kodiaq 2.0TDI 110 Sport.4x4 AT
Kodiaq 2.0TDI 110 Sport.4x4 AT
Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style
Karoq 1.5TSI 110 ACT Style AT

Octavia Com.TSI 85 Style
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Sharan 2.0 TDI 110 High.AT
Volkswagen
Volkswagen
308 SW 1.5BHDi 100 Active
Pas.Var.2.0TDI 140 Elegance AT
Kamiq 1.0TSI 85 Style
Kamiq 1.0TSI 85 Style
Kamiq 1.0TSI 85 Style
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Scala 1.0TSI 85 Ambition
Karoq 1.5TSI 110 ACT Style
Karoq 1.5TSI 110 ACT Style
Karoq 1.5TSI 110 ACT Style
Karoq 1.5TSI 110 ACT Style
Octa.Com TDI 135 Scout 4x4 AT
Octa.Com TDI 135 Scout 4x4 AT
Octa.Com TDI 135 Scout 4x4 AT
Octa.Com TDI 135 Scout 4x4 AT
Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style

Fabia Com 1.0TSI 81 Style
Fabia Com 1.0TSI 81 Style
Octa.Com TDI 135 Style 4x4 AT
Octa.Com TDI 135 Style 4x4 AT
Octa.Com TDI 135 Style 4x4 AT
Fabia 1.0TSI 70 Style
Octavia Com 1.6TDI 85 Style
Kamiq 1.5TSI 110 Style
Kamiq 1.5TSI 110 Style
Kamiq 1.5TSI 110 Style
Kamiq 1.5TSI 110 Style
Kamiq 1.5TSI 110 Style
Kamiq 1.5TSI 110 Style
Kamiq 1.5TSI 110 Style
Kamiq 1.5TSI 110 Style
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
Kodiaq 2.0TDI 140 Sport.4x4 AT
X5 3.0xDrive 30d AT
BMW
Sharan 2.0 TDI130 HL 4M AT
Sharan 2.0 TDI130 HL 4M AT

Pas.Var.2.0TDI 110 Elegance
Pas.Var.2.0TDI 110 Elegance
Pas.Var.2.0TDI 110 Elegance
Pas.Var.2.0TDI 110 Elegance
Pas.Var.2.0TDI 110 Elegance
Pas.Var.2.0TDI 110 Elegance
Pas.Var.2.0TDI 110 Elegance
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Karoq 1.6TDI 85 Style AT
Karoq 1.6TDI 85 Style AT
Karoq 1.6TDI 85 Style AT
Karoq 1.6TDI 85 Style AT
Supe.FL2.0TDI 110 Style AT
Supe.FL2.0TDI 110 Style AT
Supe.FL2.0TDI 110 Style AT
Sup.C.FL2.0TDI 110 L&K AT
Sup.C.FL2.0TDI 110 L&K AT
Sup.C.FL2.0TDI 110 L&K AT
Sup.C.FL2.0TDI 110 L&K AT
Arteon 2.0TDI 140 Elegia 4M DSG
Arteon 2.0TDI 140 Elegia 4M DSG
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Kodiaq 1.5TSI 110 Style AT
Kodiaq 1.5TSI 110 Style AT
Kodiaq 1.5TSI 110 Style AT
Octavia 2.0TDI 85 Style 5d
Octavia 2.0TDI 85 Style 5d
Octavia 2.0TDI 85 Style 5d

Octavia 2.0TDI 85 Style 5d
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
A6 35 TDI 120 Design AT
A6 35 TDI 120 Design AT
A6 35 TDI 120 Design AT
A6 35 TDI 120 Design AT
A6 35 TDI 120 Design AT
Arteon 2.0TDI 140 Rline 4M DSG
Camry 2.5Hyb. Executive AT
Camry 2.5Hyb. Executive AT
Camry 2.5Hyb. Executive AT
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Caddy 2.0TDI 110 TL DSG6
Rifter 1.5BHDI 100 Active
Rifter 1.5BHDI 100 Active
Sharan 2.0 TDI130 HL 4M AT
Sharan 2.0 TDI130 HL 4M AT
Sharan 2.0 TDI130 HL 4M AT

Megane GT 1.5dCi 115 Zen
Megane GT 1.5dCi 115 Zen
Megane GT 1.5dCi 115 Zen
Oct.Combi 2.0TDI 85 Ambition
Oct. 2.0TDI 110 Style AT 5d
Oct. 2.0TDI 110 Style AT 5d
Oct. 2.0TDI 110 Style AT 5d
Oct. 2.0TDI 110 Style AT 5d
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Camry 2.5Hyb. Executive AT
Sup.C.FL2.0TDI 140 Style AT
Sup.C.FL2.0TDI 140 Style AT
Sup.C.FL2.0TDI 140 Style AT
Sup.C.FL2.0TDI 140 Style AT
Sup.C.FL2.0TDI 140 Style AT
Sup.C.FL2.0TDI 140 Style AT
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Golf Var.2.0TDI 110 Highline
Volkswagen
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Octavia 1.5TSI 110 Ambition 5d

Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Kodiaq 2.0TDI 110 Ambition 4x4
Kodiaq 2.0TDI 110 Ambition 4x4
Kodiaq 2.0TDI 110 Ambition 4x4
Kodiaq 2.0TDI 110 Ambition 4x4
Skoda
Skoda
Fabia Com 1.0TSI 81 Style
Skoda
Rifter 1.5BHDi 100 Active
Boxer F.2.2BHDI 3300L2H2 Acces
Boxer F.2.2BHDI 3300L2H2 Acces
Boxer F.2.2BHDI 3300L2H2 Acces
Boxer F.2.2BHDI 3300L2H2 Acces
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Corolla TS 1.2T Comfort
Corolla TS 1.2T Comfort
Octavia Com TDI 110 Ambit. AT
Octavia Com TDI 110 Ambit. AT
Camry 2.5Hyb. Executive AT
Oct.Combi 1.5TSI 110 Ambition
Oct.Combi 1.5TSI 110 Ambition
Oct.Combi 1.5TSI 110 Ambition
Oct.Combi 1.5TSI 110 Ambition
Oct.Combi 1.5TSI 110 Ambition

Octavia 1.5TSI 110 Ambition 5d
Boxer F.2.2BHDI 3500 L3H2 Act.
Boxer F.2.2BHDI 3500 L3H2 Act.
Boxer F.2.2BHDI 3500 L3H2 Act.
Boxer F.2.2BHDI 3500 L3H2 Act.
Boxer F.2.2BHDI 3500 L3H2 Act.
Boxer F.2.2BHDI 3500 L3H2 Act.
Boxer F.2.2BHDI 3500 L3H2 Act.
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Fabia Com 1.0TSI 81 Ambition
Fabia Com 1.0TSI 81 Ambition
Fabia Com 1.0TSI 81 Ambition
Fabia Com 1.0TSI 81 Ambition
Oct.Combi 2.0TDI 85 Ambition
Oct.Combi 1.5TSI 110 Ambition
Oct.Combi 1.5TSI 110 Ambition
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Crafter 35 130 sredni rozvor
Boxer F.2.2BHDI 3300L2H2 Acces
Boxer F.2.2BHDI 3300L2H2 Acces

Oct.Combi 2.0TDI 85 Ambition
Octavia 2.0TDI 85 Style 5d
Octavia 2.0TDI 85 Style 5d
Octavia 2.0TDI 85 Style 5d
Octavia 2.0TDI 85 Style 5d
Octavia 2.0TDI 85 Style 5d
Octavia 2.0TDI 85 Style 5d
Oct.Combi 2.0TDI 85 Ambition
Oct.Combi 2.0TDI 85 Ambition
5008 1.5BHDi 130 Active AT
5008 1.5BHDi 130 Active AT
RAV4 2.5Hyb.218 Executive AT
RAV4 2.5Hyb.218 Executive AT
RAV4 2.5Hyb.218 Executive AT
i30 1.5 T-GDI M.Hyb Smart kom.
i30 1.5 T-GDI M.Hyb Smart kom.
i30 1.5 T-GDI M.Hyb Smart kom.
i30 1.5 T-GDI M.Hyb Smart kom.
Kodiaq 2.0TDI 140 Styl. 4x4 AT
Kodiaq 2.0TDI 140 Styl. 4x4 AT
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
i30 kom. TGDI 120 Start Plus
i30 kom. TGDI 120 Start Plus
Supe.2.0TDI 147 Style Aut
Supe.2.0TDI 147 Style Aut
Supe.2.0TDI 147 Style Aut
Supe.2.0TDI 147 Style Aut
Supe.2.0TDI 147 Style Aut

Supe.2.0TDI 147 Style Aut
Supe.2.0TDI 147 Style Aut
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.Combi 2.0TDI 85 Style
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.Combi 1.5TSI 110 Style
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Skoda
Skoda
i30 kom. TGDl 120 Start Plus
i30 kom. TGDl 120 Start Plus
Oct.1.5e-TEC 110 Ambition AT
Oct.1.5e-TEC 110 Ambition AT
Oct.1.5e-TEC 110 Ambition AT
Kodiaq 1.5TSI 110 Style AT
Tiguan 2.0 TDI 110 Elegance AT
Tiguan 2.0 TDI 110 Elegance AT
Tiguan 2.0 TDI 110 Elegance AT
Oct.Combi 1.5TSI 110 Style
Oct.Combi 1.5TSI 110 Style
Oct.Combi 1.5TSI 110 Style
Oct.Combi 1.5TSI 110 Style
Octavia 2.0TDI 85 Ambition AT
i30 k.1.6CRDi Hyb.136 Style
i30 k.1.6CRDi Hyb.136 Style
i30 k.1.6CRDi Hyb.136 Style
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT

i30 kom. TGDI 120 Start Plus
Oct.C. 2.0TDI 147 Scout 4x4 AT
GLC 300 d 4X4 AT
GLC 300 d 4X4 AT
GLC 300 d 4X4 AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Scala 1.0 TSI 81 Ambition AT
Scala 1.0 TSI 81 Ambition AT
Fabia Com.1.0TSI 70 Style
Fabia Com.1.0TSI 70 Style
Fabia Com.1.0TSI 70 Style
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Boxer F.2.2HDI 4350 L4H2 Act.
Boxer F.2.2HDI 4350 L4H2 Act.
Boxer F.2.2HDI 4350 L4H2 Act.
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Octavia 1.5TSI 110 Ambition 5d
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT
Oct.Combi 2.0TDI 110 Style AT

Oct.Combi 2.0TDI 110 Style AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Corolla TS 2.0Hyb.Comfor AT
Sup.C.FL2.0TDI 110 Style AT
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Fabia Com.1.0TSI 70 Ambition
Corolla TS 2.0Hyb.Executive AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Octavia 1.5TSI 110 Style 5d
Skoda
Berlingo BHDl 102 L1 Plus 4d
Berlingo BHDl 102 L1 Plus 4d
Berlingo BHDl 102 L1 Plus 4d
Berlingo BHDl 102 L1 Plus 4d
Berlingo BHDl 102 L1 Plus 4d
Berlingo BHDl 102 L1 Plus 4d
Scala 1.0TSI 70 Ambition
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Boxer F.2.2HDI 4350 L4H2 Act.
Boxer F.2.2HDI 4350 L4H2 Act.
Boxer F.2.2HDI 4350 L4H2 Act.
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT

Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Oct.C. 2.0TDI 147 Scout 4x4 AT
Karoq 1.5TSI 110 ACT Style AT
Kodiaq 2.0 TDI 147 L&K 4x4 AT
Kodiaq 2.0 TDI 147 L&K 4x4 AT
Kodiaq 2.0 TDI 147 L&K 4x4 AT
A6 Av.3.0TDI 45 quatt.Sport AT
A6 Av.3.0TDI 45 quatt.Sport AT
GR.X 1.5CDTI 96 Elegance 5d
GR.X 1.5CDTI 96 Elegance 5d
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Karoq 1.5TSI 110 ACT Style AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Pas.Var.2.0TDI 110 Elegance AT
Oct.Com.1.0 e-TEC 81 Ambit.AT
Oct.Com.1.0 e-TEC 81 Ambit.AT
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Octavia Com 1.6TDI 85 Style
Kamq 1.0 TSI 81 Ambition AT
Kamq 1.0 TSI 81 Ambition AT
Kamq 1.0 TSI 81 Ambition AT
Kamq 1.0 TSI 81 Ambition AT
FabiaCom.1.0TSI 70 Ambition 5d
Oct.Com.1.0 e-TEC 81 Ambit.AT

i30 kom.1.0TGDI Family Comf
i30 kom.1.0TGDI Family Comf
i30 kom.1.0TGDI Family Comf
i30 kom.1.0TGDI Family Comf
Oct. 2.0TDI 110 Style AT 5d
Oct. 2.0TDI 110 Style AT 5d
Oct. 2.0TDI 110 Style AT 5d
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Arteon 2.0TSI 200 R-line 4M AT
Tucs.1.6 T-GDI 110 Style AT
Tucs.1.6 T-GDI 110 Style AT
Berlingo BHDI 102 L1 Plus 4d
Berlingo BHDI 102 L1 Plus 4d
Ceed SW 1.5 T-GDI 118 Spin 5d
Ceed SW 1.5 T-GDI 118 Spin 5d
Ceed SW 1.5 T-GDI 118 Fresh
Ceed SW 1.5 T-GDI 118 Fresh
Ceed SW 1.5 T-GDI 118 Fresh
Karoq 1.5TSI 110 Style AT
Karoq 1.5TSI 110 Style AT
Cross.1.2T 81 Edition 5d
Cross.1.2T 81 Edition 5d
Cross.1.2T 81 Edition 5d
i30 kom.1.0TGDI Family Comf
i30 kom.1.0TGDI Family Comf
Golf Var.1.0TSI 81 Life 5d
Golf Var.1.0TSI 81 Life 5d
Tucs.1.6T-GDI 132 NLine 4x4 AT
Corolla 1.5DF Comfort 4d

Pas.Var.1.5TSI EVO Business
Sportage 1.6TGDI 110 Exclusive
Sportage 1.6TGDI 110 Exclusive
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
Corolla 1.5DF Comfort 4d
i30 2.0T-GDI 280 N Performance
Leon ST 2.0 TSI 180 AT 5d
XC60 B4 B Core AT 5d
Corolla TS 1.8Hyb GR Sport AT
Kamiq 1.5TSI 110 Ambition 5d
Superb 1.4PHEV 160 Style AT
Superb 1.4PHEV 160 Style AT
Enyaq 82 kWh Sportline AT 5d
Enyaq 82 kWh Sportline AT 5d
Sup.C.1.4 PHEV 160 L&K AT
Sup.C.1.4 PHEV 160 L&K AT
Sup.C.1.4 PHEV 160 L&K AT
Sup.C.1.4 PHEV 160 Sport L.AT
Superb 1.4PHEV 160 Sport L.AT
Superb 1.4PHEV 160 Sport L.AT
Superb 1.4PHEV 160 Sport L.AT
e-Niro 150kW Executive AT
e-Niro 150kW Executive AT
Model 3 Long Range RWD AT
ID.3 58kWh Tech AT

Model Y Long Range AWD AT
Sup.C.1.4 PHEV 160 L&K AT
Sup.C.1.4 PHEV 160 L&K AT